

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

Mr Andrew
Mr
Moray
23/8/24
d/s \$3600
Hdy s.

VEHICLE No: SLU 9507T

1PC TAILGATE
1PC BOOTLID REAR LOGO
1PC REAR BUMPER
1PC REAR BUMPER LOWER GARNISH
2PCS REAR BUMPER PDC SENSORS @\$195.00
1PC REAR BUMPER INNER TOP RETAINER
1PC REAR BUMPER REINFORCEMENT
1SET REAR BUMPER CLIPS & RIVERT
2PCS REAR BUMPER SIDE HOLDERS @\$165.00
2PCS TAILLAMPS @\$650.00
2PCS TAILLAMP LOWER BRACKETS @\$85.00
1PC REAR END PANEL

n \$1,898.20 X
na \$99.40 X
D/Tom \$1,610.68 /
graph/Tom \$455.80 /
Su \$390.00 X
cu \$211.30 /
D \$722.89 /
nu \$60.00 /
u \$330.00 X
Su \$1,300.00 X
cu \$170.00 /
n \$1,013.70 X
\$8,261.97
LESS 10% \$7,435.77

TO CHECK WIRING
TO DISMANTLE & REPLACED REAR PDC SENSOR
TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY
TO TRANSFER BOOTLID MECHANISM
TO SPRAY RUST PROOFING
TO RESET & REPROGRAMME SYSTEM
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$50.00 20
\$80.00 40
\$120.00 60
na \$100.00 X
\$90.00 20
\$100.00 80
\$900.00 580
\$1,580.00 800
TOTAL \$10,455.77

LKK Auto Consultants hence notify
the Repairer of the following:
• To rectify before/after spray painting
• To display damaged part(s) before rectify
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be rectified and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

9-323067
102
2907.60
1600
4507.6
212
3606