



AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

T : (65) 6419 3000

www.aig.sg

Claim No: 0525274003SG Date of Survey: 02/10/2023
Repairer: CYCLE & CARRIAGE INDUSTRIES PTE LTD

REFERENCE

Insured: [REDACTED] Policy No: [REDACTED]
Date of Loss: 28/09/2023 Nature of Claim: OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg. No: SLJ223D
Make & Model: MERCEDES-BENZ GLC300, 2.0 4MATIC (A) Reg. Date: 28/02/2023
Engine No: 26492080230524 Chassis No: W1N2539842G078928

CONDITION OF TYRES

Front Tyre Size:	235/60R18	Rear Tyre Size:	235/60R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable):	Yes	Engine Modification:	No		
Handbrake (Serviceable):	Yes	Steering (Serviceable):	Yes	Pre-accident Condition:	Good

TOTAL OFFER

Offer Authorized By:	TAN, JAYDEN-CK on 13 Feb 2024 14:18
Offer Initiated By:	TAN, JAYDEN-CK on 03 Oct 2023 09:14
Subrogation:	Yes
Rep. Gross Total:	S\$11,919.89 [Diff: S\$1,866.20, 15.66%]
Approved Gross Total:	S\$10,053.69
- Excess:	S\$0.00 [Waived: S\$600.00] [Remarks: Not Applicable]
	S\$10,053.69
+ GST (9.00%):	S\$904.83
Approved Nett Amount:	S\$10,958.52 (No Betterment/Depreciation)

Basis of Offer: Authorized on 02/10/2023, MBMI, Excess \$0.

COST OF CLAIMS	Repairer's	Our Offer	Difference	Diff %
Parts	7,564.89	6,234.69	1,330.20	17.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,355.00	3,819.00	536.00	12.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	

Gross Total (S\$)	11,919.89	10,053.69	1,866.20	15.66
+ GST 9.00/9.00% (S\$)	1,072.79	904.83	167.96	15.66
Nett Amount (S\$)	12,992.68	10,958.52	2,034.16	15.66

SURVEYOR'S REMARKS

This inspection is conducted on a "Without Prejudice Basis"

Estimated repair period : 5.0 days

Authorised Repair : Yes

Inspection conducted by : Tan, Jayden-CK (AIG Claims Dept)

Signature : _

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH/FRONT FENDER	DD	993.47 FL	*993.47 FL /
2	1		*RH/FRONT FENDER BLACK TRIM	Cut	292.46 FL	*292.46 FL /
3	1		*FRONT BUMPER	BR	1,468.51 FL	*1,468.51 FL /
4	1		*FRONT BUMPER LOWER BLACK TRIM		346.72 FL	*- FL
5	1		*FRONT BUMPER LOWER CHROME COVER		1,094.68 FL	*- FL
6	1		*RH/COVER, BUMPER AREA	BR	36.69 FL	*36.69 FL /
7	1		*RH/FRONT BUMPER MOUNTING RAIL	NEC	20.14 FL	*20.14 FL /
8	1		*RH/BASIC CARRIER FOR BUMPER	BR	71.34 FL	*71.34 FL /
9	1		*RH/HEADLAMP UNIT	BR	3,384.20 FL	*3,384.20 FL /
10	10		*CUPPED BLIND RIVET	NEC	55.00 FL	*55.00 FL /
11	0		*RH/HEADLAMP BOTTOM BRACKET		36.60 FL	-
12	1		*RH/HEADLAMP CONSOLE	BR	81.61 FL	*81.61 FL /
13	1		*TRIM CLIP	NEC	8.07 FL	*8.07 FL /
14	1		*CROSS MEMBER	DD	515.94 FL	*515.94 FL /

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	8,405.43	6,927.43
- List Item Discount on L Items 10.00/10.00% (S\$)	840.54	692.74
Total Parts (S\$)	7,564.89	6,234.69

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DISASSEMBLE & REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,344.00	1,008.00
2	RESPRAY FRONT BUMPER & RH/FRT FENDER	New	1,800.00	1,600.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT, RESET MEMORY TO IDEN. STD. NETT	New	380.00	380.00
4	TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT	New	96.00	96.00
5	TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT	New	540.00	540.00
6	CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS	New	180.00	180.00
7	SUNDRIES	New	15.00	15.00
Gross Labour Cost (\$\$)			4,355.00	3,819.00

AIG Asia Pacific Insurance Pte. Ltd./SLJ223D/13/02/2024 14:18

< END OF REPORT >

4 days