



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400307W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNH8528J

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#22-00
SINGAPORE 048580
63476100

WIP No 20280
Reg No/Reg Date SNH8528J / 30/11/2022
Date In/Mileage / 0
Chassis No W1K1183842N3510487
Engine No 28291480916282
Make/Model MB/CLA 180 COUPE
Colour/Trim 021 191 Cosmos Blac/ 041 111 ARTICO Leat

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator			
WI000576	Credit	04/10/2024/ 09:54	VS	356 / Vincent Seah			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE :5140148424//16.08.2024
DRIVE IN/EXCESS :20.08.2024// TP CAR NO.: SLL8606U-INDIA
DATE IN/DATE SURVEY:04.10.2024 //
DIRECT SETTLEMENT: YAN -LKK

M BPNSUN

SUDRIES

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB

TRANSFER REAR BOOT MECHANISM TO NEW PANEL

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. 960 x 1.5

A BPIRES

RESPRAY ON REAR BUMPER, BOOT AND ACCIDENT AFFECTED AREA 800 x 2

A BPILAB

TRANSFER REAR BOOT SPOILER TO NEW PANEL NETT

M REAR BUMPER

X R ?

1.00

1463.03 00.00

1463.03

M REAR LOWER BUMPER

X R ?

1.00

517.32 00.00

517.32

R TRUNK LID

X R ?

1.00

2354.89 00.00

2354.89

R MODEL PLATE

X R ?

1.00

224.29 00.00

224.29

M RELEASE HANDLE

X R ?

1.00

199.60 00.00

199.60

M MERCEDES STAR

X R ?

1.00

186.88 00.00

186.88

Steve (LKK) +6 010 9479541

4/10/24, 11.00am

m p/p

Confirmed & accepted by

by Bob Smy

5 days

sterchen@lkk auto. com

9% GST on 10621.01 955.89

Total Payable 11,576.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 120378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNH8528J

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#22-00
SINGAPORE 048580
63476100

Vehicle & Document Information

WIP No	20280
Reg No/Reg Date	SNH8528J / 30/11/2022
Date In/Mileage	04/10/2024/ 29722
Chassis No	W1K1183842N3510487
Engine No	28291480916282
Make/Model	MB/CLA 180 COUPE
Colour/Trim	021 191 Cosmos Blac/ 041 111 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator
WI000576	Credit	13/12/2024/ 10:01	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE :5140148424//16.08.2024 DRIVE IN/EXCESS :20.08.2024// TP CAR NO.: SLL8606U-INDIA DATE IN/DATE SURVEY:04.10.2024 // 04.10.2024 STEVE-LKK 11:00AM DIRECT SETTLEMENT: YAN -LKK X SPRING DAMPER	2.00	17.50	00.00	Nec 35.00 /

SUPPLEMENTARY

Confirmed & accepted by

	Nett	35.00
9% GST on	35.00	3.15
Total Payable		38.15

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNH8528J

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#22-00
SINGAPORE 048580
63476100

Vehicle & Document Information
WIP No 20280
Reg No/Reg Date SNH8528J / 30/11/2022
Date In/Mileage 04/10/2024/ 29722
Chassis No W1K1183842N3510487
Engine No 28291480916282
Make/Model MB/CLA 180 COUPE
Colour/Trim 021 191 Cosmos Blac/ 041 111 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WI000576	Credit	13/12/2024/ 10:01	VS	356 / Vincent Seah					
Z REQUEST									
Customer Request									
M BPNSUN									
POLICY NO/ACC DATE :5140148424//16.08.2024									
DRIVE IN/EXCESS :20.08.2024// TP CAR NO.: SLL8606U-INDIA									
DATE IN/DATE SURVEY:04.10.2024 // 04.10.2024 STEVE-LKK 11:00AM									
DIRECT SETTLEMENT: YAN -LKK									
M BPNSUN									
SUDRIES									15.00
A BPILAB									
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								0.10	380.00
A BPILAB									240.00
TRANSFER REAR BOOT MECHANISM TO NEW PANEL									1440.00
A BPILAB									1600.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.									240.00
A BPIRES								0.05	2354.89
RESPRAY ON REAR BUMPER, BOOT AND ACCIDENT AFFECTED AREA									224.29
A BPILAB									35.00
TRANSFER REAR BOOT SPOILER TO NEW PANEL NETT									
X TRUNK LID						1.00	2354.89	00.00	2354.89
X MODEL PLATE						1.00	224.29	00.00	224.29
X SPRING DAMPER						2.00	17.50	00.00	35.00

Finalization

5 days

Confirmed & accepted by

9% GST on **Nett** 6,529.18
587.63

Authorized signatory and company stamp

Total Payable 7,116.81

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg