

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

23/8/2024

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINAGPORE 068877

Vehicle No: SLU428Y

Vehicle Model: T/HARRIER

Est No: CBMQ24080211

Claims ref:

Accident Date: 16/08/24

In Charge: JUNIOR

Remarks:

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	TAILGATE - REPAIR	1	PC	\$ -
2	TAILGATE EMBLEM "HARRIER" <i>neu</i>	1	PC \$ 90.00	\$ 90.00 ✓
3	TAILGATE EMBLEM "TUBRO" <i>neu</i>	1	PC \$ 130.00	\$ 130.00 ✓
4	REAR BUMPER <i>de</i>	1	PC \$ 910.00	\$ 910.00 ✓
5	REAR BUMPER SPONGE <i>? x m</i>	1	PC \$ 160.00	\$ 160.00
6	RR BUMPER REINFORCEMENT - CHECK	1	PC	\$ -
7	REAR BUMPER LOWER GARNISH <i>de</i>	1	PC \$ 470.00	\$ 470.00 ✓
8	RR BUMPER REFLECTOR LH & RH <i>x m</i>	2	PC \$ 90.00	\$ 180.00
9	RR BUMPER CENTER BRACKET - CHECK	1	PC	\$ -
10	RR BUMPER LOW BRKT RH & LH - CHECK	1	PC	\$ -
11	REVERSE SENSOR INNER RH & LH <i>? x m</i>	2	PC \$ 480.00	\$ 960.00
12	REVERSE SENSOR BRKT LH & RH <i>? x m</i>	2	PC \$ 40.00	\$ 80.00
13	REAR BUMPER CLIPS <i>re</i>	10	PC \$ 5.00	\$ 50.00 ✓
14	REAR END PANEL <i>requi pleho?</i>	1	PC \$ 1,280.00	\$ 1,280.00 <i>x R</i>
15	REAR BUMPER INNER CLIPS <i>re</i>	4	PC \$ 5.00	\$ 20.00 ✓
16	RR SPARE TYRE COMPARTMENT - REPAIR	1	PC	\$ -
LIST TOTAL S\$				\$ 4,330.00
25% DISCOUNT S\$				\$ (1,082.50)
				<u>\$ 3,247.50</u>

1670
25%
1252.50

LABOUR CHARGE:

- TO CUT, WELD, PANEL BEAT, STRAIGHTEN, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS
\$ 900.00
400 + 200 = 600
- TO PUTTY SPRAY PAINT ON TAILGATE, REAR BUMPER, REVERSE SENSOR LH & RH, REAR END PANEL, REAR SPARE TYRE COMPARTMENT
\$ 900.00
600
- TO APPLY SPRAY TEROSTAT SEALANT ON REAR END PANEL,

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

23/8/2024

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINAGPORE 068877

Vehicle No: SLU428Y
Vehicle Model: T/HARRIER
Est No: CBMQ24080211
Claims ref:
Accident Date: 16/08/24
In Charge: JUNIOR
Remarks:

No	Description	Qty	U. Price	Amounts S\$
	& REAR SPARE TYRE COMPARTMENT			\$ 80.00 <i>X4n</i>
4	TO RESET REPROGRAMMING AFTER ACCIDENT REPAIR WORKS			\$ 180.00 <i>80.00</i>
5	TO CHECK ELECTRICAL & WIRING SYSTEM FOR PROPER FUNTION			\$ 80.00 <i>Xnq</i>
6	TO RUST PROOF ON TAILGATE, REAR SPARE TYRE COMPARTMENT			\$ 100.00 <i>Xm</i>
	TOTAL LABOUR COST S\$		1300	\$ 2,240.00

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

AMOUNT S\$ \$ 5,487.50
GST @ 9% \$ 493.88
AMOUNT DUE S\$ \$ 5,981.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Resurvey is on a "Without Prejudice" basis
- Confirmation(s) is allowed
- Resurvey must be resurveyed on
- Confirmation(s) must be resurveyed on

Acknowledged by Repairer
Signature:

Panel
Ap 900 no 68
3 days
L/S
2042
\$2000/3days
27/08/24
Resy after repair