

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

23/8/2024

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINAGPORE 068877

Vehicle No: SLU428Y
Vehicle Model: T/HARRIER
Est No:CBMQ24080211
Claims ref:
Accident Date: 16/08/24
In Charge: JUNIOR
Remarks:

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	TAILGATE - REPAIR	1	PC	\$ -
2	TAILGATE EMBLEM "HARRIER "	1	PC \$ 90.00	\$ 90.00
3	TAILGATE EMBLEM "TUBRO "	1	PC \$ 130.00	\$ 130.00
4	REAR BUMPER	1	PC \$ 910.00	\$ 910.00
5	REAR BUMPER SPONGE	1	PC \$ 160.00	\$ 160.00
6	RR BUMPER REINFORCEMENT - CHECK	1	PC	\$ -
7	REAR BUMPER LOWER GARNISH	1	PC \$ 470.00	\$ 470.00
8	RR BUMPER REFLECTOR LH & RH	2	PC \$ 90.00	\$ 180.00
9	RR BUMPER CENTER BRACKET - CHECK	1	PC	\$ -
10	RR BUMPER LOW BRKT RH & LH - CHECK	1	PC	\$ -
11	REVERSE SENSOR INNER RH & LH	2	PC \$ 480.00	\$ 960.00
12	REVERSE SENSOR BRKT LH & RH	2	PC \$ 40.00	\$ 80.00
13	REAR BUMPER CLIPS	10	PC \$ 5.00	\$ 50.00
14	REAR END PANEL	1	PC \$ 1,280.00	\$ 1,280.00
15	REAR BUMPER INNER CLIPS	4	PC \$ 5.00	\$ 20.00
16	RR SPARE TYRE COMPARTMENT - REPAIR	1	PC	\$ -
LIST TOTAL S\$				\$ 4,330.00
25% DISCOUNT S\$				\$ (1,082.50)
				<u>\$ 3,247.50</u>

LABOUR CHARGE:

1	TO CUT, WELD,PANEL BEAT, STRAIGHTEN, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS	\$ 900.00
2	TO PUTTY SPRAY PAINT ON TAILGATE, REAR BUMPER, REVERSE SENSOR LH & RH, REAR END PANEL, REAR SPARE TYRE COMPARTMENT	\$ 900.00
3	TO APPLY SPRAY TEROSTAT SEALANT ON REAR END PANEL,	

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2


ESTIMATE

23/8/2024

MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Vehicle No: SLU428Y
 Vehicle Model: T/HARRIER
 Est No: CBMQ24080211
 Claims ref:
 Accident Date: 16/08/24
 In Charge: JUNIOR
 Remarks:

No	Description	Qty	U. Price	Amounts S\$
	& REAR SPARE TYRE COMPARTMENT			\$ 80.00
4	TO RESET REPROGRAMMING AFTER ACCIDENT REPAIR WORKS			\$ 180.00
5	TO CHECK ELECTRICAL & WIRING SYSTEM FOR PROPER FUNTION			\$ 80.00
6	TO RUST PROOF ON TAILGATE, REAR SPARE TYRE COMPARTMENT			\$ 100.00
	TOTAL LABOUR COST S\$			<u>\$ 2,240.00</u>

Customer's Signature		AMOUNT S\$	\$ 5,487.50
	MOVA AUTOMOTIVE PTE LTD	GST @ 9%	\$ 493.88
		AMOUNT DUE S\$	<u>\$ 5,981.38</u>