



Final Report

Estimate No. : **b1 70958**
Date Estimated : **22/08/2024**
Prepared By : **Chua Kee Sin**

Page No. :

- ESTIMATE REPAIR FOR -

Khoa Hee Tiang
Apt Blk 434 Tampines Street 43
#03-79

Singapore 520434

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
SFA6733C	WBY42AW000FR14754	25/08/2023	I4 EDRIIVE35 GRAN COUPE	30380

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper panel, RH air curtain include carrying out other necessary repairs caused by the accident	850.00	0.00	850.00
To spray paint front bumper	1,038.00	0.00	1,038.00
To check electrical wiring system of the front section for proper function	177.00	0.00	177.00
To replace RH high intensity headlight include functionality programming and conducting checks for proper function	481.00	0.00	481.00
Sundries	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER PANEL PRIMED (PDC/PMA)	1,106.80	1.00	0.00	1,106.80
RH AIR CURTAIN	55.50	1.00	0.00	55.50
PLAQUE 74MM	76.55	1.00	0.00	76.55
RH HEADLIGHT LED TECHNOLOGY	3,129.45	1.00	0.00	3,129.45
DECOUPLING RING	5.65	6.00	0.00	33.90

SUPPLEMENTARY ITEMS

Total Labour :	2,626.00
Total Parts :	4,402.20
Total Labour & Parts (before GST) :	7,028.20
Deduction for Excess :	
Total Repair Costs less Excess:	7,028.20
GST @9%:	632.54
Grand Total :	7,660.74

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

