



Your Ref : SNM24D204743/C01

Date: 11th September 2024

Our Ref : CS/CTI24080412/Nnh3m4

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLN 5752P
ACCIDENT ON 22/08/2024**

Instruction was received to inspect the vehicle Reg. No. SLN 5752P. The inspection was conducted on 26/08/2024 at the premises of M/s Vin's Motor Pte Ltd, 160 Sin Ming Drive #03-03 Sin Ming Auto City, Singapore 575722.

The following vehicle information was recorded:

Registration Number	: SLN 5752P
Make/Model	: Mercedes Benz E220D Se Auto
Year of Registration	: 2017
Body Colour	: Black
Chassis Number	: WDD2130042A185927
Engine Capacity	: 1950 cc
Speedometer Reading	: N/A (Battery melted)

The vehicle caught fire. The cause of fire probably due to electrical short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	94,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	46,479.00)
Nett Liability	S\$	47,521.00
	=====	

Vehicle Inspected By:



MUHD NAZRIL (NAZ)
Technical Investigator
LL.B. (Hons) London



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.