

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 19.08.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMV2878B**
MODEL : **KIA CERATO FORTE**
DATE OF ACCIDENT : 18.08.2024
TIME OF ACCIDENT : 19:20 HOURS

Yan.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Distorted</i>	1	\$ 698.00	\$ 698.00
2	REAR BUMPER BRACKET <i>New</i>	5	\$ 22.00	\$ 110.00
3	REAR BUMPER SIDE RETAINER <i>LH Distorted</i>	2	\$ 16.00	\$ 32.00
4	REAR BUMPER CENTER GARNISH <i>Distorted</i>	1	\$ 246.00	\$ 246.00
5	REAR BUMPER REINFORCEMENT BRACKET <i>LH Distorted</i>	2	\$ 72.00	\$ 144.00
6	REAR BUMPER REINFORCEMENT <i>Distorted</i>	1	\$ 394.00	\$ 394.00
7	REAR BUMPER SPONGE <i>Distorted</i>	1	\$ 189.00	\$ 189.00
8	TAIL LAMP <i>LH Distorted</i>	2	\$ 342.00	\$ 684.00
9	TAIL LAMP PANEL LH <i>Distorted</i>	1	\$ 190.00	\$ 190.00
10	REAR FENDER LH <i>Distorted</i>	1	\$ 935.00	\$ 935.00
11	REAR FENDER INNER PANEL LH <i>Repair</i>	1	\$ 912.00	\$ 912.00
12	REAR FENDER AIR VENT LH <i>Missing</i>	1	\$ 98.20	\$ 98.20
13	REAR FENDER INNER COWLING <i>torn LH</i>	2	\$ 98.00	\$ 196.00
14	REAR FENDER INNER TRIM <i>LH torn</i>	2	\$ 232.00	\$ 464.00
15	REAR WINDSCREEN MOULDING <i>New</i>	1	\$ 135.00	\$ 135.00
16	REAR DOOR LH <i>Distorted</i>	1	\$ 1,170.00	\$ 1,170.00
17	REAR DOOR INNER LH <i>221</i>	1	\$ 986.00	\$ 1,170.00
18	REAR DOOR WEATHER STRIP LH <i>New</i>	1	\$ 150.00	\$ 150.00
19	REAR DOOR INNER LOCK LH	1	\$ 360.00	\$ 360.00
20	BOOT LID <i>Distorted</i>	1	\$ 897.00	\$ 897.00
21	BOOT LID MOULDING <i>New</i>	1	\$ 292.00	\$ 292.00

16.
72.
342
198.
232

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMV2878B**
 MODEL : **KIA CERATO FORTE**
 DATE OF ACCIDENT : 18.08.2024
 TIME OF ACCIDENT : 19:20 HOURS

22	BOOT LID LAMP <i>LH cut</i>	2	\$ 226.00	\$ 452.00	226.
23	BOOT LID LOGO <i>new</i>	1	\$ 65.00	\$ 65.00	✓
24	BOOT LID EMBLEM "CERATO" <i>3 new</i>	1	\$ 43.00	\$ 43.00	✓
25	BOOT LID EMBLEM "FORTE"	1	\$ 58.00	\$ 58.00	✓
26	BOOT LID STOPPER <i>new</i>	2	\$ 19.00	\$ 38.00	+
27	BOOT LID HINGE <i>new</i>	2	\$ 68.00	\$ 136.00	+
28	BOOT LID INSULATOR <i>new</i>	1	\$ 231.00	\$ 231.00	+
29	BOOT LID WEATHER STRIP <i>cut</i>	1	\$ 148.00	\$ 148.00	✓
30	BOOT LID LOCK <i>new</i>	1	\$ 127.00	\$ 127.00	+
31	BOOT LID LOWER LOCK <i>new</i>	1	\$ 25.00	\$ 25.00	+
32	REAR END PANEL <i>Dehnd</i>	1	\$ 382.00	\$ 382.00	✓
33	REAR END PANEL TOP GARNISH <i>Dehnd</i>	1	\$ 143.00	\$ 143.00	✓
34	REAR FLOOR PANEL <i>Not in</i>	1	\$ 896.00	\$ 896.00	+
35	REAR FLOOR SIDE PANEL LH <i>Repair</i>	1	\$ 438.00	\$ 438.00	+
36	REAR FLOOR PANEL TOP BOARD <i>torn</i>	1	\$ 241.00	\$ 241.00	✓
37	REVERSE SENSOR <i>2 pieces damaged</i>	2	\$ 312.00	\$ 624.00	✓
38	REVERSE SENSOR HOLDER <i>new</i>	4	\$ 52.00	\$ 208.00	100
39	REVERSE SENSOR WIREHARNESS <i>new</i>	1	\$ 496.00	\$ 496.00	X

7742.20
6967.98

TOTAL PRICE \$ 14,217.20
 LESS 10% \$ 1,421.72
SUB TOTAL PRICE \$ 12,795.48

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
4	BOOT LID MOULDING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
5	BOOT LID INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
6	BOOT LID EMBLEM 'C&C' (SPECIAL TYPE) <i>new</i>	1	\$ 150.00	\$ 150.00
7	REAR DOOR LH SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
8	REAR DOOR INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
9	REAR FENDER LH SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
10	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
11	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
12	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMV2878B**
 MODEL : **KIA CERATO FORTE**
 DATE OF ACCIDENT : 18.08.2024
 TIME OF ACCIDENT : 19:20 HOURS

13	REAR WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	<i>40</i>
14	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
15	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>10</i>
16	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
17	REVERSE SENSOR (SET) <i>Repaired</i>	1	\$ 220.00	\$ 220.00	<i>+</i>

355 TOTAL \$ 1,840.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS	\$ 2,200.00	<i>1300</i>
2	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS	\$ 1,800.00	<i>1000</i>
3	TUFF COAT	\$ 250.00	<i>120</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	<i>80</i>
6	TRANSFER REAR DOOR MECHANISM	\$ 80.00	<i>60</i>
7	REMOVE AND REFIX REAR WINDSCREEN	\$ 150.00	<i>120</i>
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
9	TRANSFER BOOTLID MECHANISM	\$ 80.00	<i>60</i>
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>X</i>
11	REMOVE AND REFIX FUEL TANK TO FACILITATE REPLACEMENT	\$ 80.00	<i>60</i>

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMV2878B**
MODEL : **KIA CERATO FORTE**
DATE OF ACCIDENT : 18.08.2024
TIME OF ACCIDENT : 19:20 HOURS

12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	
----	--	-----------	--

TOTAL \$ **5,530.00**

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,635.48
TOTAL LABOUR COST : \$ 5,530.00
TOTAL REPAIR COST : \$ 20,165.48

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

Adrian L
L/S 20/08/24.
09 Days.

Total: 10202.98
L/S: 8150 ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: