

ASSIGNMENT

Fronte _____ Date: _____
 Estin _____
 OD / 2 PHS / TP RES / CD RES / EVA / INV / MV
 To in _____ Vehicle No: _____
 at W _____ m/s
 of _____
 Insured: _____
 Policy No _____
 Claims No _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Vch _____
 (Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SMV 2878B Yr Regn: 2010, Sept
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Icia Gerato Forle C.D. 1591
 Colour Bronze A/C: Insured / Std / NI / NA
 Sp. Reading 190088 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KNAFW411MA5275632
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45R17
 R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Roadstone

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.J. 20/08/24
 Survey held at J2 Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Reas N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>78 AIG</u>
	<u>COE Expiry : 29/05/2025</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV : 101C</u>
	<u>PV : 3.7K</u>
	<u>Nett : 6.3K</u>
	<u>205C</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS \$1 _____

Photos _____

Others _____

Report Format: _____

Report Format: _____

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail: jlperfectautowork@gmail.com



DATE : 19.08.2024

TO	: AIG MOTOR CLAIMS DEPTS
VEHICLE NO	: SMV2878B
MODEL	: KIA CERATO FORTE
DATE OF ACCIDENT	: 18.08.2024
TIME OF ACCIDENT	: 19:20 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Distorted</i>	1	\$ 698.00	\$ 698.00
2	REAR BUMPER BRACKET <i>New</i>	5	\$ 22.00	\$ 110.00
3	REAR BUMPER SIDE RETAINER <i>LH Distorted</i>	2	\$ 16.00	\$ 32.00
4	REAR BUMPER CENTER GARNISH <i>Distorted</i>	1	\$ 246.00	\$ 246.00
5	REAR BUMPER REINFORCEMENT BRACKET <i>LH Distorted</i>	2	\$ 72.00	\$ 144.00
6	REAR BUMPER REINFORCEMENT <i>Cracked</i>	1	\$ 394.00	\$ 394.00
7	REAR BUMPER SPONGE <i>Cracked</i>	1	\$ 189.00	\$ 189.00
8	TAIL LAMP <i>LH Cracked</i>	2	\$ 342.00	\$ 684.00
9	TAIL LAMP PANEL LH <i>Distorted</i>	1	\$ 190.00	\$ 190.00
10	REAR FENDER LH <i>Distorted</i>	1	\$ 935.00	\$ 935.00
11	REAR FENDER INNER PANEL LH <i>Repair</i>	1	\$ 912.00	\$ 912.00
12	REAR FENDER AIR VENT LH <i>Missing</i>	1	\$ 98.20	\$ 98.20
13	REAR FENDER INNER COWLING <i>tooth LH</i>	2	\$ 98.00	\$ 196.00
14	REAR FENDER INNER TRIM <i>LH torn</i>	2	\$ 232.00	\$ 464.00
15	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 135.00	\$ 135.00
16	REAR DOOR LH <i>Repair Distorted</i>	1	\$ 1,170.00	\$ 1,170.00
17	REAR DOOR INNER LH <i>2 set</i>	1	\$ 986.00	\$ 1,170.00
18	REAR DOOR WEATHER STRIP LH <i>new</i>	1	\$ 150.00	\$ 150.00
19	REAR DOOR INNER LOCK LH	1	\$ 360.00	\$ 360.00
20	BOOT LID <i>Distorted</i>	1	\$ 897.00	\$ 897.00
21	BOOT LID MOULDING <i>new</i>	1	\$ 292.00	\$ 292.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMV2878B**
 MODEL : **KIA CERATO FORTE**
 DATE OF ACCIDENT : 18.08.2024
 TIME OF ACCIDENT : 19:20 HOURS

22	BOOT LID LAMP <i>LH cut</i>	2	\$ 226.00	\$ 452.00	✓ 226
23	BOOT LID LOGO <i>new</i>	1	\$ 65.00	\$ 65.00	✓
24	BOOT LID EMBLEM "CERATO" <i>3 new</i>	1	\$ 43.00	\$ 43.00	✓
25	BOOT LID EMBLEM "FORTE" <i>1</i>	1	\$ 58.00	\$ 58.00	✓
26	BOOT LID STOPPER <i>new</i>	2	\$ 19.00	\$ 38.00	+
27	BOOT LID HINGE <i>new</i>	2	\$ 68.00	\$ 136.00	+
28	BOOT LID INSULATOR <i>new</i>	1	\$ 231.00	\$ 231.00	+
29	BOOT LID WEATHER STRIP <i>cut</i>	1	\$ 148.00	\$ 148.00	✓
30	BOOT LID LOCK <i>new</i>	1	\$ 127.00	\$ 127.00	+
31	BOOT LID LOWER LOCK <i>new</i>	1	\$ 25.00	\$ 25.00	+
32	REAR END PANEL <i>Rehnd</i>	1	\$ 382.00	\$ 382.00	✓
33	REAR END PANEL TOP GARNISH <i>Rehnd</i>	1	\$ 143.00	\$ 143.00	✓
34	REAR FLOOR PANEL <i>Rehnd</i>	1	\$ 896.00	\$ 896.00	+
35	REAR FLOOR SIDE PANEL LH <i>Rehnd</i>	1	\$ 438.00	\$ 438.00	+
36	REAR FLOOR PANEL TOP BOARD <i>torn</i>	1	\$ 241.00	\$ 241.00	✓
37	REVERSE SENSOR <i>2 pieces damaged</i>	2	\$ 312.00	\$ 624.00	✓
38	REVERSE SENSOR HOLDER <i>new</i>	4	\$ 52.00	\$ 208.00	✓ 100
39	REVERSE SENSOR WIREHARNES <i>✓</i>	1	\$ 496.00	\$ 496.00	

TOTAL PRICE \$ 14,217.20
 LESS 10% \$ 1,421.72
SUB TOTAL PRICE \$ 12,795.48

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00	+
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	✓ 30
3	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
4	BOOT LID MOULDING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	BOOT LID INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
6	BOOT LID EMBLEM 'C&C' (SPECIAL TYPE) <i>new</i>	1	\$ 150.00	\$ 150.00	✓ 45
7	REAR DOOR LH SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
8	REAR DOOR INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
9	REAR FENDER LH SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	✓ 60
10	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	✓ 20
11	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	✓ 30
12	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	✓ 60

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMV2878B**
 MODEL : **KIA CERATO FORTE**
 DATE OF ACCIDENT : 18.08.2024
 TIME OF ACCIDENT : 19:20 HOURS

13	REAR WINDSCREEN INNER SEAL <i>nw</i>	1	\$ 60.00	\$ 60.00	<i>40</i>
14	REAR END PANEL INSULATION SEAL <i>nw</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
15	REAR END PANEL TOP GARNISH CLIP (SET) <i>nw</i>	1	\$ 30.00	\$ 30.00	<i>10</i>
16	REAR FLOOR PANEL INSULATION SEAL <i>nw</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
17	REVERSE SENSOR (SET) <i>Reported</i>	1	\$ 220.00	\$ 220.00	<i>+</i>

TOTAL \$ 1,840.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS	\$ 2,200.00	<i>1300</i>
2	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS	\$ 1,800.00	<i>1000</i>
3	TUFF COAT	\$ 250.00	<i>120</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	<i>80</i>
6	TRANSFER REAR DOOR MECHANISM	\$ 80.00	<i>60</i>
7	REMOVE AND REFIX REAR WINDSCREEN	\$ 150.00	<i>120</i>
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
9	TRANSFER BOOTLID MECHANISM	\$ 80.00	<i>60</i>
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>+</i>
11	REMOVE AND REFIX FUEL TANK TO FACILITATE REPLACEMENT	\$ 80.00	<i>60</i>

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMV2878B**
MODEL : **KIA CERATO FORTE**
DATE OF ACCIDENT : 18.08.2024
TIME OF ACCIDENT : 19:20 HOURS

12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>A</i>
----	--	-----------	----------

TOTAL \$ **5,530.00**

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,635.48
TOTAL LABOUR COST : \$ 5,530.00
TOTAL REPAIR COST : \$ 20,165.48

Abdul
2/5 20/08/24.
09 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: