



FALCON - AIR

ANG JIT HOCK @ SAID ALWI ANG
 C/O 176 SIN MING DRIVE #01-06/07
 SIN MING AUTOCARE
 575721

Tel : 96743764

*Not Authorized
 L1 Rep & 2950h
 Murray After Paint
 4 days*

Estimate : ES000095
 Date : 28/08/2024
 Vehicle No. : SLU5390M
 Vehicle Model : TOYOTA ALTIS ELEGANCE
 Chassis No. : MR053REH604576003
 Accident Date : 26/08/2024
 Claim No. :
 Reference : TP GEG AGT MINDEF
 Policy No. : V5010280
 Page : 1 of 2

Item	Qty	Description	Unit Price S\$	Amount S\$
			1,408.00	1,408.00 X
1.	1	RH HEADLAMP	523.00	523.00 X
2.	1	FRONT BUMPER	68.00	68.00 X
3.	1	RH FRONT BUMPER SIDE RETAINER	675.00	675.00 ✓
4.	1	RH FRONT FENDER	62.00	62.00 ✓
5.	1	RH FRONT FENDER EMBLEM	208.00	208.00 X
6.	1	RH FRONT FENDER INNER SHIELD	899.00	899.00 ✓
7.	1	RH SIDE MIRROR ASSY	1,263.00	1,263.00 ✓
8.	1	RH FRONT DOOR	107.00	214.00
9.	2	RH FRONT DOOR HINGE	88.00	88.00 ✓
10.	1	RH FRONT DOOR BLACK STICKER	1,728.00	1,728.00 ✓
11.	1	RH FRONT RIM	280.00	280.00 ✓
12.	1	RH FRONT TYRE	189.00	189.00 ✓
13.	1	RH FRONT WHEEL BEARING		-1,901.25
		Discount 25 %		5,703.75
		SubTotal	60.00	60.00 X
14.	1	FRONT BUMPER CLIP	60.00	60.00 ✓
15.	1	RH FRONT FENDER INNER SHIELD CLIP	50.00	50.00 201
16.	1	TO CHECK WIRING AND FOCUS HEADLAMP	100.00	100.00 X
17.	1	TO REMOVE/REFIX RH FRONT DOOR MECHANISM		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

FALCON - AIR AUTO SERVICES PTE LTD
 (a subsidiary of Falcon Air Services Pte Ltd)



FALCON - AIR

ANG JIT HOCK @ SAID ALWI ANG
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE
575721

Tel : 96743764

Estimate : ES000095
Date : 28/08/2024
Vehicle No. : SLU5390M
Vehicle Model : TOYOTA ALTIS ELEGANCE
Chassis No. : MR053REH604576003
Accident Date : 26/08/2024
Claim No. :
Reference : TP GEG AGT MINDEF
Policy No. : V5010280
Page : 2 of 2

Item	Qty	Description	Unit Price S\$	Amount S\$
18.	1	COMPUTERISE WHEEL ALIGNMENT	120.00	601 120.00
19.	1	TO REMOVE/REFIT TYRE TO NEW RIM AND BALANCING	50.00	201 50.00
20.	1	TO REMOVE NECESSARY PARTS, TO REPAIR INNER PANEL, REPLACE DAMAGE PARTS AND ALIGN THE SAME	600.00	4001 600.00
21.	1	TO PUTTY AND RESPRAY FRONT BUMPER, RH FRONT FENDER, RH FRONT DOOR	700.00	6501 700.00

SINGAPORE DOLLAR EIGHT THOUSAND ONE HUNDRED THIRTEEN AND CENTS SIXTY NINE ONLY

Total S\$ 7,443.75

Notes :

- All cheques should be crossed and made payable to FALCON-AIR AUTO SERVICES PTE LTD
- Goods sold are neither returnable nor refundable. Otherwise a cancellation fee of 20% on purchase price will be imposed.

Accepted by

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg