

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0471/2024/EQ
DATE : 18-Jun-24
WIP : 19776

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 21/06/2024.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian,

4 Days - OK - Allan Boo

13-Sep-24

OWNER'S NAME : MR. CHEUNG JOE FAI
ADDRESS : 52 TOH TUCK ROAD
#06-05
SINGAPORE 596743
TELEPHONE : HP +65 96488203
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7230102731
VEHICLE NO : **SCA 2388 C**
MODEL CODE : AUDI Q2 1.5 TFSI S-TRONIC
MODEL YEAR : 31/10/2023
ENGINE NO : DPC F00107
CHASSIS NO : WAUZZZGAXNA013028
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Jun-24
PLACE OF ACCIDENT : BUKIT TIMAH PLAZA CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCA 2388 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	\$ 280.00
2	TO DISMANTLE AND RENEW RHS REAR DOOR. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,000.00	\$ 500.00
3	TO RESPRAY RHS REAR DOOR, RHS REAR FENDER, RHS REAR DOOR HANDLE AND FUEL FILLER FLAP.	\$	2,500.00	\$ 1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$ 292.00
TOTAL LABOUR CHARGES		: \$	5,192.00	\$ 2,172.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCA 2388 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR DOOR - RH	1	\$ 3,152.00	\$	2,521.60
2	REAR DOOR OUTER SEAL - RH	1	\$ 275.00	\$	220.00
3	BONDING AGENT	1	\$ 54.00		
4	CLEANING SOLUTION	1	\$ 92.00		
5	APPLICATOR	1	\$ 10.00		
6	REAR DOOR ATTACHMENT PARTS	1	\$ 110.00		
7	REAR DOOR CATCH - RH	1	\$ 150.00		
8	REAR DOOR COVER - RH	1	\$ 267.00	\$	213.60
9	REAR DOOR EXTERIOR HANDLE - RH	1	\$ 460.00		
10	REAR DOOR EXTERIOR HANDLE HOUSING - RH	1	\$ 83.00		
11	REAR DOOR EXTERIOR HANDLE SLIDE VALVE - RH	1	\$ 28.00		
12	REAR DOOR EXTERIOR HANDLE UNDERLAY - RH FRONT	1	\$ 7.00		
13	REAR DOOR EXTERIOR HANDLE UNDERLAY - RH REAR	1	\$ 8.00		
14	REAR DOOR EXTERIOR HANDLE MOUNTING BAR - RH	1	\$ 186.00		
15	REAR DOOR LOCK - RH	1	\$ 682.00		
16	REAR WHEEL ARCH COVER - RH	1	\$ 202.00		
17	SUNDRIES		\$ 500.00		
TOTAL SPARE PARTS			\$ 6,266.00	\$	2,955.20
TOTAL LABOUR CHARGES			\$ 5,192.00	\$	2,172.00
GRAND TOTAL			\$ 11,458.00	\$	5,127.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT