

Company Reg No: 202136905K

**Tel: 6341 6789      Fax: 6341 6778**  
**E-mail: [ilperfectautowork@gmail.com](mailto:ilperfectautowork@gmail.com)**



DATE : 19.08.2024

|                  |   |                           |                    |
|------------------|---|---------------------------|--------------------|
| TO               | : | <b>AIG</b>                | MOTOR CLAIMS DEPTS |
| VEHICLE NO       | : | <b>SNL4782Y</b>           |                    |
| MODEL            | : | <b>TOYOTA YARIS CROSS</b> |                    |
| DATE OF ACCIDENT | : | 16.08.2024                |                    |
| TIME OF ACCIDENT | : | 14:25                     | HOURA              |

Xiao Tong  
2021  
mXPJ103008263

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| CLAIM DETAIL - PARTS |                                                 |     |                 |                  |
|----------------------|-------------------------------------------------|-----|-----------------|------------------|
| S/N                  | DESCRIPTION                                     | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
| 1                    | REAR BUMPER (UPPER) <i>3 Deformed</i>           | 1   | \$ 485.40       | \$ 485.40        |
| 2                    | REAR BUMPER (LOWER)                             | 1   | \$ 498.10       | \$ 498.10        |
| 3                    | REAR BUMPER REFLECTOR <i>new</i>                | 2   | \$ 110.30       | \$ 220.60        |
| 4                    | REAR BUMPER LOWER CENTER COVER <i>torn</i>      | 1   | \$ 498.00       | \$ 498.00        |
| 5                    | REAR BUMPER SIDE RETAINER <i>new</i>            | 2   | \$ 98.30        | \$ 196.60        |
| 6                    | TAILGATE <i>Deformed</i>                        | 1   | \$ 1,280.10     | \$ 1,280.10      |
| 7                    | TAILGATE REFLECTOR <i>3 rep</i>                 | 2   | \$ 196.70       | \$ 393.40        |
| 8                    | TAILGATE LAMP <i>4 new</i>                      | 2   | \$ 331.60       | \$ 663.20        |
| 9                    | TAILGATE DAMPER                                 | 2   | \$ 211.50       | \$ 423.00        |
| 10                   | TAILGATE INNER HOLDER <i>new</i>                | 1   | \$ 69.30        | \$ 69.30         |
| 11                   | TAIL GATE LOGO <i>new</i>                       | 1   | \$ 81.70        | \$ 81.70         |
| 12                   | TAILGATE EMBLEM 'YARIS' <i>green</i>            | 1   | \$ 98.70        | \$ 98.70         |
| 13                   | TAILGATE EMBLEM 'CROSS'                         | 1   | \$ 93.30        | \$ 93.30         |
| 14                   | TAILGATE STOPPER <i>new</i>                     | 2   | \$ 38.10        | \$ 76.20         |
| 15                   | TAILGATE TOP LOCK <i>2 new</i>                  | 1   | \$ 268.10       | \$ 268.10        |
| 16                   | TAILGATE LOWER LOCK <i>new</i>                  | 1   | \$ 68.00        | \$ 68.00         |
| 17                   | TAILGATE INNER TRIM <i>new</i>                  | 1   | \$ 651.30       | \$ 651.30        |
| 18                   | TAILGATE WEATHER STRIP <i>at</i>                | 1   | \$ 285.70       | \$ 285.70        |
| 19                   | TAILGATE WINDSCREEN MOULDING (SET) <i>2 new</i> | 1   | \$ 191.30       | \$ 191.30        |
| 20                   | TAIL LAMP <i>2H new</i>                         | 2   | \$ 495.30       | \$ 990.60        |
| 21                   | TAIL LAMP LOWER BRACKET <i>new</i>              | 2   | \$ 48.30        | \$ 96.60         |

—  
 —  
 +  
 310  
 +  
 —  
 +  
 +  
 +  
 +  
 +  
 +  
 ✓  
 ✓  
 +  
 —  
 X  
 ✓  
 ✓  
 ✓  
 —495.30  
 X

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SNL4782Y**  
 MODEL : **TOYOTA YARIS CROSS**  
 DATE OF ACCIDENT : 16.08.2024  
 TIME OF ACCIDENT : 14:25 HOURS

|    |                                           |   |           |             |
|----|-------------------------------------------|---|-----------|-------------|
| 22 | REAR FENDER INNER TRIM <i>RH crumpled</i> | 2 | \$ 511.30 | \$ 1,022.60 |
| 23 | REAR FENDER COWLING <i>3x4</i>            | 2 | \$ 126.70 | \$ 253.40   |
| 24 | REAR FENDER ARCED GARNISH <i>3x4</i>      | 2 | \$ 281.60 | \$ 563.20   |
| 25 | REAR END PANEL <i>Dented</i>              | 1 | \$ 516.40 | \$ 516.40   |
| 26 | REAR END PANEL TOP GARNISH <i>Dented</i>  | 1 | \$ 516.40 | \$ 516.40   |
| 27 | REAR FLOOR PANEL <i>Right</i>             | 1 | \$ 865.70 | \$ 865.70   |
| 28 | REAR FLOOR PANEL CENTRE SPONGE <i>new</i> | 1 | \$ 217.60 | \$ 217.60   |
| 29 | REAR FLOOR PANEL TOP BOARD <i>Dented</i>  | 1 | \$ 317.60 | \$ 317.60   |
| 30 | REAR TOOLS SPONGE <i>new</i>              | 2 | \$ 167.40 | \$ 334.80   |
| 31 | REVERSE SENSOR <i>2 pieces crumpled</i>   | 4 | \$ 223.60 | \$ 894.40   |
| 32 | REVERSE SENSOR HOLDER <i>2 pieces new</i> | 4 | \$ 67.00  | \$ 268.00   |
| 33 | REVERSE SENSOR WIRE HARNESS <i>new</i>    | 1 | \$ 476.80 | \$ 476.80   |

TOTAL PRICE \$ 13,876.10  
 LESS 25% \$ 3,469.03  
**SUB TOTAL PRICE \$ 10,407.08**

#### SPECIAL NETT ITEMS

| S/N | DESCRIPTION                                            | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|--------------------------------------------------------|-----|-------------|--------------|
| 1   | REAR NUMBER PLATE <i>new</i>                           | 1   | \$ 50.00    | \$ 50.00     |
| 2   | REAR BUMPER CLIP (SET) <i>new</i>                      | 1   | \$ 80.00    | \$ 80.00     |
| 3   | REAR BUMPER LOWER CENTRE GARNISH CLIP (SET) <i>new</i> | 1   | \$ 50.00    | \$ 50.00     |
| 4   | REAR BUMPER REFLECTOR GARNISH CLIP (SET) <i>new</i>    | 1   | \$ 50.00    | \$ 50.00     |
| 5   | REAR SPOILER CLIP (SET) <i>new</i>                     | 1   | \$ 80.00    | \$ 80.00     |
| 6   | TAIL LAMP CLIP (SET) <i>new</i>                        | 1   | \$ 30.00    | \$ 30.00     |
| 7   | TAILGATE SEALANT <i>new</i>                            | 1   | \$ 150.00   | \$ 150.00    |
| 8   | TAILGATE OUTER GARNISH CLIP (SET) <i>new</i>           | 1   | \$ 30.00    | \$ 30.00     |
| 9   | TAILGATE INNER TRIM BOARD CLIP (SET) <i>new</i>        | 1   | \$ 50.00    | \$ 50.00     |
| 10  | TAILGATE WINDSCREEN SEALANT <i>3x4</i>                 | 1   | \$ 80.00    | \$ 80.00     |
| 11  | TAILGATE WINDSCREEN INNER SEAL <i>3x4</i>              | 1   | \$ 60.00    | \$ 60.00     |
| 12  | REAR FENDER INNER TRIM CLIP (SET) <i>new</i>           | 1   | \$ 80.00    | \$ 80.00     |
| 13  | REAR FENDER COWLING CLIP (SET) <i>new</i>              | 1   | \$ 80.00    | \$ 80.00     |
| 14  | REAR FENDER ARCED GARNISH CLIP (SET) <i>new</i>        | 1   | \$ 50.00    | \$ 50.00     |
| 15  | REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>      | 1   | \$ 30.00    | \$ 30.00     |
| 16  | REAR END PANEL INSULATION SEAL <i>new</i>              | 1   | \$ 150.00   | \$ 150.00    |

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SNL4782Y**  
 MODEL : **TOYOTA YARIS CROSS**  
 DATE OF ACCIDENT : 16.08.2024  
 TIME OF ACCIDENT : 14:25 HOURS

|    |                                             |   |           |           |          |
|----|---------------------------------------------|---|-----------|-----------|----------|
| 17 | REAR FLOOR PANEL INSULATION SEAL <i>new</i> | 1 | \$ 150.00 | \$ 150.00 | <i>+</i> |
| 18 | REVERSE CAMERA <i>new</i>                   | 1 | \$ 450.00 | \$ 450.00 | <i>+</i> |

*240*

**TOTAL \$ 1,700.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

| S/N | JOB DESCRIPTION                                                                | PRICE       | ADJUSTED COST |
|-----|--------------------------------------------------------------------------------|-------------|---------------|
| 1   | PANEL BEATING, REMOVAL AND REPLACING PARTS                                     | \$ 2,000.00 | <i>800</i>    |
| 2   | TO SPRAY PAINT AFFECTED AREA                                                   | \$ 1,800.00 | <i>700</i>    |
| 3   | TUFF COAT                                                                      | \$ 350.00   | <i>60</i>     |
| 4   | REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR | \$ 250.00   | <i>60</i>     |
| 5   | REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING                           | \$ 80.00    | <i>50</i>     |
| 6   | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                           | \$ 80.00    | <i>50</i>     |
| 7   | REAR CHASSIS ALIGNMENT                                                         | \$ 180.00   | <i>X</i>      |
| 8   | REMOVE AND REFIX TAILGATE WINDSCREEN                                           | \$ 120.00   | <i>✓</i>      |
| 9   | TRANSFER TAILGATE MECHANISM                                                    | \$ 150.00   | <i>60</i>     |
| 10  | CONDUCT WATER LEAKAGE TEST                                                     | \$ 80.00    | <i>X</i>      |
| 11  | REMOVE AND REFIX REAR EXHAUST PIPE                                             | \$ 120.00   | <i>X</i>      |

TO : **AIG** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SNL4782Y**  
MODEL : **TOYOTA YARIS CROSS**  
DATE OF ACCIDENT : 16.08.2024  
TIME OF ACCIDENT : 14:25 HOURS

|    |                                                                                                      |           |   |      |
|----|------------------------------------------------------------------------------------------------------|-----------|---|------|
| 12 | TO CHECK DIAGNOSTICS OF VEHICLE<br>MANAGEMENT/CONTROL UNITS, RESET<br>MEMORIES TO SPECIFICATION ETC. | \$ 250.00 | X | 1780 |
|----|------------------------------------------------------------------------------------------------------|-----------|---|------|

**TOTAL** \$ **5,460.00**

TOTAL PARTS COST : \$ 12,107.08  
TOTAL LABOUR COST : \$ 5,460.00  
TOTAL REPAIR COST : \$ 17,567.08

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE  
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED  
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
IRENE  
HP : 8297 9787

total: 7018.35  
H/S: 5.7K

5.7K

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: