

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 19.08.2024

TO	: AIG MOTOR CLAIMS DEPTS
VEHICLE NO	: SNL4782Y
MODEL	: TOYOTA YARIS CROSS
DATE OF ACCIDENT	: 16.08.2024
TIME OF ACCIDENT	: 14:25 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER (UPPER) <i>3 Dehd</i>	1	\$ 485.40	\$ 485.40
2	REAR BUMPER (LOWER)	1	\$ 498.10	\$ 498.10
3	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 110.30	\$ 220.60
4	REAR BUMPER LOWER CENTER COVER <i>torn</i>	1	\$ 498.00	\$ 498.00
5	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 98.30	\$ 196.60
6	TAILGATE <i>Dented</i>	1	\$ 1,280.10	\$ 1,280.10
7	TAILGATE REFLECTOR <i>3 rep</i>	2	\$ 196.70	\$ 393.40
8	TAILGATE LAMP <i>4 new</i>	2	\$ 331.60	\$ 663.20
9	TAILGATE DAMPER	2	\$ 211.50	\$ 423.00
10	TAILGATE INNER HOLDER <i>new</i>	1	\$ 69.30	\$ 69.30
11	TAIL GATE LOGO <i>new</i>	1	\$ 81.70	\$ 81.70
12	TAILGATE EMBLEM 'YARIS' <i>3 new</i>	1	\$ 98.70	\$ 98.70
13	TAILGATE EMBLEM 'CROSS'	1	\$ 93.30	\$ 93.30
14	TAILGATE STOPPER <i>new</i>	2	\$ 38.10	\$ 76.20
15	TAILGATE TOP LOCK <i>2 new</i>	1	\$ 268.10	\$ 268.10
16	TAILGATE LOWER LOCK <i>not new</i>	1	\$ 68.00	\$ 68.00
17	TAILGATE INNER TRIM <i>crackd</i>	1	\$ 651.30	\$ 651.30
18	TAILGATE WEATHER STRIP <i>at</i>	1	\$ 285.70	\$ 285.70
19	TAILGATE WINDSCREEN MOULDING (SET) <i>2 new</i>	1	\$ 191.30	\$ 191.30
20	TAIL LAMP <i>2H crackd</i>	2	\$ 495.30	\$ 990.60
21	TAIL LAMP LOWER BRACKET <i>new</i>	2	\$ 48.30	\$ 96.60

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNL4782Y**
 MODEL : **TOYOTA YARIS CROSS**
 DATE OF ACCIDENT : 16.08.2024
 TIME OF ACCIDENT : 14:25 HOURS

22	REAR FENDER INNER TRIM <i>RH curved</i>	2	\$ 511.30	\$ 1,022.60
23	REAR FENDER COWLING <i>gap</i>	2	\$ 126.70	\$ 253.40
24	REAR FENDER ARCED GARNISH <i>Jan</i>	2	\$ 281.60	\$ 563.20
25	REAR END PANEL <i>Dented</i>	1	\$ 516.40	\$ 516.40
26	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 516.40	\$ 516.40
27	REAR FLOOR PANEL <i>Regr</i>	1	\$ 865.70	\$ 865.70
28	REAR FLOOR PANEL CENTRE SPONGE <i>new</i>	1	\$ 217.60	\$ 217.60
29	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$ 317.60	\$ 317.60
30	REAR TOOLS SPONGE <i>new</i>	2	\$ 167.40	\$ 334.80
31	REVERSE SENSOR <i>2 pieces dented</i>	4	\$ 223.60	\$ 894.40
32	REVERSE SENSOR HOLDER <i>2 pieces new</i>	4	\$ 67.00	\$ 268.00
33	REVERSE SENSOR WIRE HARNESS <i>new</i>	1	\$ 476.80	\$ 476.80

TOTAL PRICE \$ 13,876.10
 LESS 25% \$ 3,469.03
SUB TOTAL PRICE \$ 10,407.08

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR BUMPER LOWER CENTRE GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	REAR BUMPER REFLECTOR GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
5	REAR SPOILER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
6	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
7	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
8	TAILGATE OUTER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
9	TAILGATE INNER TRIM BOARD CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
10	TAILGATE WINDSCREEN SEALANT <i>green</i>	1	\$ 80.00	\$ 80.00
11	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
12	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
13	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
14	REAR FENDER ARCED GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
15	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
16	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNL4782Y**
 MODEL : **TOYOTA YARIS CROSS**
 DATE OF ACCIDENT : 16.08.2024
 TIME OF ACCIDENT : 14:25 HOURS

17	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
18	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	<i>+</i>

TOTAL \$ 1,700.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	<i>700</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>700</i>
3	TUFF COAT	\$ 350.00	<i>60</i>
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	<i>60</i>
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REAR CHASSIS ALIGNMENT	\$ 180.00	<i>X</i>
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>
9	TRANSFER TAILGATE MECHANISM	\$ 150.00	<i>60</i>
10	CONDUCT WATER LEAKAGE TEST	\$ 80.00	<i>X</i>
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 120.00	<i>X</i>

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNL4782Y**
MODEL : **TOYOTA YARIS CROSS**
DATE OF ACCIDENT : 16.08.2024
TIME OF ACCIDENT : 14:25 HOURS

12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X
----	--	-----------	---

TOTAL \$ 5,460.00

TOTAL PARTS COST : \$ 12,107.08
TOTAL LABOUR COST : \$ 5,460.00
TOTAL REPAIR COST : \$ 17,567.08

Adrian CJ
1/8 20/08/24
06 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: