

Company Reg No: 202136904Z

E-mail: hdperfectautowork@gmail.com



**HD PERFECT
AUTOWORK PTE LTD**

DATE : 19.08.2024

TO	: AIG MOTOR CLAIMS DEPTS
VEHICLE NO	: GBF8473K
MODEL	: TOYOTA HIACE
DATE OF ACCIDENT	: 14.08.2024
TIME OF ACCIDENT	: 07:25 HOURS

Daphne

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL - PARTS					
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	FRONT BUMPER <i>Distorted</i>	1	\$ 495.70	\$ 495.70	
2	FRONT BUMPER LOWER SIDE GRILLE <i>new</i>	1	\$ 195.40	\$ 195.40	
3	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 238.10	\$ 238.10	
4	FRONT BUMPER SIDE RETAINER <i>LH angled</i>	2	\$ 180.00	\$ 360.00	
5	HEADLAMP <i>angled RH</i>	2	\$ 758.00	\$ 1,516.00	
6	FRONT CORNER PANEL LH <i>new</i>	1	\$ 389.70	\$ 389.70	
7	FRONT CENTRE GRILLE BASE	1	\$ 894.20	\$ 894.20	
8	FRONT CENTRE GRILLE GARNISH (UPPER) <i>for</i>	1	\$ 249.50	\$ 249.50	
9	FRONT CENTRE GRILLE GARNISH (LOWER)	1	\$ 429.50	\$ 429.50	
10	FRONT WINDSCREEN MOULDING <i>new</i>	1	\$ 120.00	\$ 120.00	
11	FRONT DOOR PILLAR (OUTER) LH <i>Distorted</i>	1	\$ 984.90	\$ 984.90	
12	FRONT DOOR PILLAR (INNER) LH <i>new</i>	1	\$ 896.20	\$ 896.20	
13	FRONT DOOR STEP PANEL GARNISH LH <i>lt</i>	1	\$ 198.10	\$ 198.10	
14	FRONT DOOR STEP PANEL LH <i>Distorted</i>	1	\$ 235.00	\$ 235.00	
15	FRONT DOOR LH <i>Distorted</i>	1	\$ 1,983.70	\$ 1,983.70	
16	FRONT DOOR INNER LOCK LH <i>new</i>	1	\$ 469.80	\$ 469.80	
17	FRONT DOOR INNER TRIM LH <i>angled</i>	1	\$ 847.90	\$ 847.90	
18	FRONT DOOR LOCK CATCHER LH <i>new</i>	1	\$ 25.20	\$ 25.20	
19	FRONT DOOR WEATHER STRIP LH <i>new</i>	1	\$ 164.60	\$ 164.60	
20	FRONT DOOR OUTER STRIP LH <i>new</i>	1	\$ 137.40	\$ 137.40	
21	FRONT DOOR ARCED RUBBER LH <i>new</i>	1	\$ 136.80	\$ 136.80	

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBF8473K**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 14.08.2024
 TIME OF ACCIDENT : 07:25 HOURS

22	FRONT WIRE ADAPTOR HOLDER LH <i>Good</i>	1	\$	94.60	\$	94.60	✓
23	FRONT MUDFLAP LH <i>new</i>	1	\$	159.60	\$	159.60	+
24	FRONT WHEEL ARCH RUBBER LH <i>new</i>	1	\$	92.20	\$	92.20	+
25	FRONT WHEEL CAP LH <i>lt</i>	1	\$	213.80	\$	213.80	✓
26	FRONT LOWER ARM LH <i>But new</i>	1	\$	497.40	\$	497.40	+
27	FRONT UPPER ARM LH <i>But</i>	1	\$	464.30	\$	464.30	✓
28	FRONT KNUCKLE ARM LH <i>But</i>	1	\$	672.10	\$	672.10	✓
29	FRONT WHEEL HUB LH <i>But</i>	1	\$	349.70	\$	349.70	✓
30	FRONT WHEEL BEARING LH <i>But</i>	1	\$	268.10	\$	268.10	✓
31	FRONT SHOCK ABSORBER LH <i>new</i>	1	\$	379.80	\$	379.80	+
32	FRONT STABILIZER LINKAGE LH <i>new</i>	1	\$	160.00	\$	160.00	+
33	CENTER PILLAR (OUTER) RH <i>Rep</i>	1	\$	692.00	\$	692.00	+
34	SLIDING DOOR LH <i>Rep</i>	1	\$	2,290.60	\$	2,290.60	+
35	SLIDING DOOR INNER LOCK (BACK) LH <i>gap</i>	1	\$	499.30	\$	499.30	+
36	SLIDING DOOR STOPPER (SET) <i>new</i>	2	\$	62.10	\$	124.20	+

70% 70

\$315.02

TOTAL PRICE \$ 17,925.40
 LESS 25% \$ 4,481.35
SUB TOTAL PRICE \$ 13,444.05

S/N	DESCRIPTION	QTY	UNIT	S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>new</i>	1	\$	50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$	80.00	\$ 80.00
3	FRONT DOOR SEALANT <i>new</i>	1	\$	80.00	\$ 80.00
4	FRONT DOOR INNER TRIM CLIP (SET) <i>new</i>	1	\$	80.00	\$ 80.00
5	FRONT DOOR COMPANY STICKER (SPECAIL TYPE) <i>new</i>	1	\$	550.00	\$ 550.00
6	FRONT DOOR SIDE LININNG (SPECAIL TYPE) <i>new</i>	1	\$	200.00	\$ 200.00
7	FRONT DOOR LTA STICKER LH <i>new</i>	1	\$	80.00	\$ 80.00
8	WHEEL TYRE LH <i>new</i>	1	\$	380.00	\$ 380.00
9	WHEEL RIM LH <i>new</i>	1	\$	550.00	\$ 550.00
10	FRONT WINDSCREEN SEALANT <i>new</i>	1	\$	150.00	\$ 150.00
11	FRONT WINDSCREEN INNER SHIELD <i>new</i>	1	\$	120.00	\$ 120.00
12	SILIDING DOOR COMPANY STICKER <i>new</i>	1	\$	1,200.00	\$ 1,200.00
13	DOOR VISOR (SET) <i>new</i>	1	\$	350.00	\$ 350.00

1010

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBF8473K**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 14.08.2024
 TIME OF ACCIDENT : 07:25 HOURS

TOTAL \$ 3,870.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,200.00	800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00	700
3	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	60
4	TUFF COAT	\$ 450.00	80
5	REFOCUS HEADLAMP BEAM	\$ 60.00	x
6	REMOVER AND REFIX FRONT WINDSCREEN GLASS	\$ 150.00	x
7	REMOVE AND REFIX DASHBOARD	\$ 650.00	x
8	RESET RADIO SYSTEM	\$ 150.00	x
9	TRANFER FRONT DOOR MECHANISM	\$ 80.00	40
10	REMOVE AND REFIX FRONT DOOR WINDOR GLASS	\$ 120.00	40
11	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 680.00	200
12	TO PREE FRONT WHEEL BEARING	\$ 80.00	x
13	FOUR WHEEL ALIGNMNET	\$ 120.00	80

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBF8473K**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 14.08.2024
TIME OF ACCIDENT : 07:25 HOURS

14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL \$ **7,170.00**

ESTIMATE REPORT

TOTAL PARTS COST : \$ 17,314.05
TOTAL LABOUR COST : \$ 7,170.00
TOTAL REPAIR COST : \$ 24,484.05

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP: 8297 9787

Adrian
21/08/24
10 Days
2000

total: 8325.02

2/5: 6650

6650

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: