



Pal Line Pte. Ltd

Attention: Owner
Contact:

COMPLETE VMS PTE LTD

5, Soon Lee Street, #01-54, Singapore 627607
(Tel) 6555 8111 (Fax) 6554 0012 (Web) www.completevms.com.sg

The Premier One Stop Vehicle Accident Claims Centre

ESTIMATE

ES 012158

Date

24/8/2024

Vehicle Number

GBL9219R

Make / Model

TOYOTA HIACE VAN TURBO 5DR MT

Engine Number

1KDB063978

Chassis Number

JTFHT02P000250897

Accident_Date

19 Aug 2024

Policy Number

5120414785-03

Description

Qty

Unit Price

Amount

Parts

List Items

Front Bumper Retainer R/H <i>cm</i>	1	S\$65.00	S\$48.75
Front Bumper <i>de</i>	1	S\$985.00	S\$738.75
Front Door R/H <i>bt</i>	1	S\$3,250.70	S\$2,438.03
Front Door Hinge Lower R/H <i>X</i>	1	S\$160.70	S\$120.53
Front Door Hinge Upper R/H <i>X</i>	1	S\$160.70	S\$120.53
Front Door Check R/H <i>X</i>	1	S\$250.30	S\$187.73
Front Door Control Panel R/H <i>X</i>	1	S\$401.20	S\$300.90
Front Rims Cover R/H <i>X</i>	1	S\$288.20	S\$216.15
Front Headlamp R/H <i>bn</i>	1	S\$1,228.40	S\$921.30
Front Headlamp Bracket R/H <i>?</i>	1	S\$27.90	S\$20.93
Bonnet <i>repair</i>	1	S\$1,386.90	S\$1,040.18
Front A Pillar R/H <i>repair</i>	1	S\$589.10	S\$441.83
Bonnet Hinge L/H & R/H <i>X</i>	2	S\$89.20	S\$133.80
Front Radiator Grille <i>X</i>	1	S\$875.00	S\$656.25
Front Lower Grille <i>X</i>	1	S\$325.00	S\$243.75
Front Logo <i>X</i>	1	S\$95.20	S\$71.40

Discount 25% applied

\$7,700.78

Special Nett Items

Company Information Stickers <i>see</i>	1	S\$180.00	S\$180.00 <i>100 30</i>
Windscreen Sealant <i>X</i>	1	S\$120.00	S\$120.00 <i>X</i>
Front Door Sticker R/H <i>see</i>	1	S\$250.00	S\$250.00 <i>100</i>
Front Bonnet Sticker <i>see</i>	1	S\$400.00	S\$400.00 <i>200</i>

Pages

1 / 2

COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which may be require after the work has begin



Pal Line Pte. Ltd

Attention: Owner
Contact:

COMPLETE VMS PTE LTD
5, Soon Lee Street, #01-54, Singapore 627607
(Tel) 6555 6111 (Fax) 6554 0012 (Web) www.completevms.com.sg
The Premier One Stop Vehicle Accident Claims Centre

ESTIMATE ES 012158
Date 24/8/2024
Vehicle Number GBL9219R
Make / Model TOYOTA HIACE VAN TURBO 5DR MT
Engine Number 1KDB063978
Chassis Number JTFHT02P000250897
Accident Date 19 Aug 2024
Policy Number 5120414785-03

Description	Qty	Unit Price	Amount
Front Radiator Grille Clip X	10	S\$6.50	S\$65.00
			\$1,015.00

Labour

Remove And Reinstall Windscreen X	1	S\$180.00	S\$180.00 X
Labour Charge To Change Door Mechanism To Facilitate Repair	1	S\$250.00	S\$250.00
Labour Charge To Change All Necessary Part	1	S\$1,000.00	S\$1,000.00
Spray Paint All Affected Area	1	S\$1,200.00	S\$1,200.00
Rust Proofing	1	S\$120.00	S\$120.00
			\$2,750.00

Total \$11,465.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 9001068
7 days
4s
27/08/24
Reg after repair

Pages

2 / 2

COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which may be require after the work has begin