



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24080420/Rvh3m4
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	19/09/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 7861E	Veh. Inspected	GBL 9219R
Policy No.	-	Coverage	0
Claim No.	BVS24/0590	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	23/08/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE	C.C	2982
Engine No.	1KDB063978	Year of Reg.	15/01/2021
Chassis No.	JTFHT02P000250897	Colour	RED
Odometer	99360 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15C	BRIDGESTONE	6
L/H Front Tyre	195R15C	BRIDGESTONE	6
R/H Rear Tyre	195R15C	BRIDGESTONE	6
L/H Rear Tyre	195R15C	BRIDGESTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/08/2024	Inspection Date	27/08/2024
Survey held at	COMPLETE VMS PTE LTD - 5 SOON LEE STREET, #01-54, SINGAPORE 627607		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days