

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #09-16
AIG BUILDING

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: TAM, IVAN-WK

Date: 21/10/2024

PRELIMINARY ADVICE

| | | | |
|-----------------|---------------------------|-------------------------|--------------|
| Vehicle No | SLW 8552H | Accident Date | 15/06/2024 |
| Make | HONDA VEZEL HYBRID 1496cc | CLAIM No. | 6111286235SG |
| Assignment Date | 18/06/2024 | Excess | - |
| Inspection Date | 19/6/2024 | Est. Duration of Repair | 6 |

Inspected At: Fong Motors

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|---------------------------|----|-----------|
| Workshop Estimate Amount: | \$ | 16,157.72 |
| Revised Estimate Amount: | \$ | 7,133.60 |
| "Check" Items Amount | | \$0.00 |
| Total | \$ | 7,133.60 |

Total Loss Consideration

| | |
|-------------------|--------|
| Book Value | \$0.00 |
| Market Value | \$0.00 |
| COE / PARF Rebate | |
| Salvage Value | \$0.00 |
| Margin for Repair | |

Remarks

- [] The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- [] The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- [] Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.