

Not Withheld
Runway B4 paint

AAD2408-027

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5891B

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

26 AUG 2024

2117.35

SHC5891B

JTDKB3FU603092678

200303878K

TOYOTA

PRIUS GEN 4

5/8/2024

SHB5233G/STRIDES

30/11/2021

PART	
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	COVER, REAR BUMPER, LOWER
1	GUARD, REAR BUMPER, CENTER
1	RETAINER, REAR BUMPER SIDE, LH
1	RETAINER, REAR BUMPER SIDE, RH
1	REFLECTOR ASSY, REFLEX, LH
1	REFLECTOR ASSY, REFLEX, RH
1	COVER, FLOOR UNDER, NO.1 LH
1	COVER, FLOOR UNDER, NO.2 RH
1	COVER, REAR FLOOR CTR
1	COVER, DECK TRIM, REAR
1	PANEL SUB-ASSY, BODY LOWER BACK
1	PANEL SUB-ASSY, BACK DOOR
1	WEATHERSTRIP, BACK DOOR
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1	STAY ASSY, BACK DOOR, LH
1	STAY ASSY, BACK DOOR, RH
1	HINGE ASSY, BACK DOOR, LH
1	HINGE ASSY, BACK DOOR, RH
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
1	PLATE, BACK DOOR NAME, NO.1
1	ORNAMENT SUB-ASSY, BACK DOOR

LIST	
\$	Bu 612.68
\$	R 419.90
\$	na 27.93
\$	R 472.19
\$	Sn 167.48 X
\$	Sn 167.48 X
\$	Sn 49.25 X
\$	Sn 49.25 X
\$	Sn 220.50 X
\$	Sn 304.92 X
\$	mgmt 290.43
\$	Sn 159.39
\$	R 824.46
\$	R 1,443.86
\$	Sn 469.25
\$	Sn 1,156.89
\$	Sn 305.66
\$	Sn 305.66
\$	R 77.18
\$	R 77.18
\$	na 68.88
\$	na 68.88
\$	na 90.30
TOTAL \$	7,829.60
25% \$	1,957.40
\$	5,872.20

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT

\$	Set 700.00	220.00
\$	na 95.00	60.00
\$	na 150.00	X

AAD2408-027

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5891B

- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR
- 2 SEAM SEALANT
- 1SET REAR BUMPER RETAINER CLIP
- 1 END PANEL TRIM CLIP

\$	nn	200.00	}	X
\$	nn	130.00		
\$	nn	80.00		
\$	nn	80.00		
\$	nn	180.00		
\$	nn	250.00		
\$	nn	85.00	}	
\$	nn	65.00		

TOTAL \$ 2,015.00

TOTAL PARTS \$ 7,887.20

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 200/

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ nn 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 180.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 200/

To reinstall rear bumper parking sensor.

\$ 170.00 50/

To Check Electrical Lighting Concerned.

\$ 170.00 X

TOTAL \$ 5,030.00

Over All Total \$ 12,917.20

LKK Auto Consultants hence notify the Repairer of the following:

- * To resurvey before/after spray painting
- * To inspect damaged part(s) during resurvey
- * Parts used are subject to confirmation
- * To proceed with work on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- * Any extra work must be resurveyed and approved to final approval from Insurance Company

As acknowledged by Repairer

Signature:

at:

(PART-BY-PART) Repair Days

8 DAYS

2 days