



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC1337  
Vehicle No. : SGS6667D  
Make & Model : MAZDA CX-3

Page No. 1

| QTY                       | DESCRIPTION                                                           | CONDITION | REPAIRER'S ESTIMATE(\$)   | SURVEYOR'S ADJUSTMENT |
|---------------------------|-----------------------------------------------------------------------|-----------|---------------------------|-----------------------|
| <b>PARTS (LIST ITEMS)</b> |                                                                       |           |                           |                       |
| 1                         | Boot lid <i>lt</i>                                                    |           | 1194.00                   | <i>1089.90</i>        |
| 1                         | Boot lid lock <i>X</i>                                                |           | 232.00 <i>X</i>           |                       |
| 1                         | Boot lid open switch <i>X</i>                                         |           | 118.00 <i>X</i>           |                       |
| 1                         | Boot lid weatherstrip <i>X</i>                                        |           | 193.00 <i>X</i>           |                       |
| 1                         | Boot lid camera <i>7.com</i>                                          |           | <del>911.00</del>         | <i>s/n-400</i>        |
| 1                         | Boot lid logo <i>new</i>                                              |           | 66.00 <i>✓</i>            |                       |
| 1                         | Boot lid emblem "CX-3" <i>new</i>                                     |           | 68.00 <i>✓</i>            |                       |
| 1                         | Boot lid emblem "SKYACTIV TECHNOLOGY" <i>new</i>                      |           | 68.00 <i>✓</i>            |                       |
| 2                         | Tail lamp RH/LH@2*\$1661 <i>X</i>                                     |           | 3322.00 <i>X</i>          |                       |
| 1                         | Rear bumper <i>de</i>                                                 |           | 1194.00                   | <i>1089</i>           |
| 2                         | Rear bumper side retainer RH/LH@2*\$27 <i>X</i>                       |           | 54.00 <i>X</i>            |                       |
| 1                         | Rear bumper lower garnish <i>X</i>                                    |           | 49.00 <i>X</i>            |                       |
| 2                         | Rear bumper lower garnish sensor RH/LH@2*\$160 <i>short (1p) @136</i> |           | 320.00                    | <i>136</i>            |
| 2                         | Rear reflector RH/LH@2*\$175 <i>X</i>                                 |           | 350.00 <i>X</i>           |                       |
| 1                         | End panel top garnish <i>7.X</i>                                      |           | 106.00 <i>X</i>           |                       |
| 1                         | Rear reinforcement <i>7.6t</i>                                        |           | 398.00                    | <i>363</i>            |
| 1                         | End panel <i>7.X</i>                                                  |           | 557.00 <i>X</i>           |                       |
| 1                         | Boot lid lock antenna <i>X</i>                                        |           | 120.00 <i>X</i>           |                       |
|                           |                                                                       |           | <b>9320.00</b>            |                       |
| <b>Part Items Total:</b>  |                                                                       |           | <b>-20%</b>               |                       |
|                           |                                                                       |           | <b>-1864.00</b>           |                       |
|                           |                                                                       |           | <b>7456.00</b>            |                       |
| <b>SPECIAL NETT ITEMS</b> |                                                                       |           |                           |                       |
| 1                         | Rear windscreen sealant <i>new</i>                                    |           | 60.00 <i>80</i>           |                       |
| 1                         | Rear bumper clip <i>new</i>                                           |           | 35.00 <i>✓</i>            |                       |
| 1                         | Rear bumper lower garnish clip <i>X</i>                               |           | 30.00 <i>X</i>            |                       |
| 1                         | End panel sealant <i>7.X</i>                                          |           | <i>40?</i> 60.00 <i>X</i> |                       |
| 1                         | car plate with holder <i>X</i>                                        |           | 35.00 <i>X</i>            |                       |
| <b>SN Items Total:</b>    |                                                                       |           | <b>220.00</b>             |                       |
| <b>Total Parts:</b>       |                                                                       |           | <b>7676.00</b>            |                       |



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC1337  
Vehicle No. : SGS6667D  
Make & Model : MAZDA CX-3

Page No. 2

| S/N                     | DESCRIPTION                                                                                                                                       | REPAIRER'S ESTIMATE (\$) | SURVEYOR'S ADJUSTMENT |
|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-----------------------|
|                         | <b>LABOUR</b>                                                                                                                                     |                          |                       |
| 1                       | To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components | <del>1000.00</del>       | 400                   |
| 2                       | To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired                                                   | <del>1000.00</del>       | 400                   |
| 3                       | To remove and refix wiring system at accident damaged area and check for all electrical                                                           | <del>90.00</del>         | <del>40</del> X       |
| 4                       | To remove and replace rear reverse sensor                                                                                                         | <del>100.00</del>        | 40                    |
| 5                       | To remove and refit rear windscreen                                                                                                               | 120.00                   |                       |
| 6                       | To perform anti-rust treatment on affected areas                                                                                                  | <del>60.00</del>         | 40                    |
| Labour Total :          |                                                                                                                                                   | 2370.00                  |                       |
| TOTAL (PARTS & LABOUR): |                                                                                                                                                   | 10046.00                 |                       |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

2303.92

400.00

75.00

1000.00

3778.92

20%

3023.13

4/5 - \$3,000 / 4 days Resurvey after repair

Rasul

Hp 90010068

4 days

4/5

29/08/24