

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile MS SOMPO INSURANCE SINGAPORE PL Ref: CS3/SMO24080430/Uqp3m4 50 RAFFLES PLACE #03-03 Date: 30/10/2024 SINGAPORE LAND TOWER SINGAPORE 048623 Code: SMO 1. **Policy Particulars :- PRE-REPAIR SURVEY** Insured Veh. SJG 3254J Veh. Inspected FBN 865Z Policy No. D22MTPV01020456 0 Coverage Claim No. CMTD2402762/AGC **Excess** \$0.00 **GRACE** 26/08/2024 Assign From **Assign Date** 2. **Vehicle Details** HONDA WW150 (PCX150) C.C 153 Make & Model 11/07/2018 KF18E5051357 Engine No. Year of Reg. WHITE Chassis No. RLHKF18A4JY202952 Colour IN ORDER Odometer 57682 KM Steering **Brakes** IN ORDER General GOOD RIMS: SPORTS RIM Modification(s) 3. Conditions of Tyres Size Make Balance (mm) 90-80-14 TIMSUN R/H Front Tyre 6 L/H Front Tyre 100-90-14 **MAXXIS** 6 R/H Rear Tyre L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR, FRONT PORTION AND N/S BODY. 5. General Information **Accident Date** 24/08/2024 **Inspection Date** 30/08/2024 (12:42) Survey held at **EQBH PTE LTD** 25 KAKI BUKIT ROAD 4 #03-46 SYNERGY @ KB SINGAPORE 417800 Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 5b. **Estimate Days of Repair**

CKS

MARCUS CHUA KANG SENG Licensed Appraiser

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days