

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIG24080431/AVP3E2**Date:** 23/01/2025REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7990000183   |
| <b>Claimant Vehicle No :</b> | SMR1169S                             | <b>Insured Vehicle No :</b> | GBF5674S     |
| Date of Loss:                | 19/08/2024                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 9366055703SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMR1169S</b>                   | Engine No:  | 26491530075941    |
| Make & Model:               | MERCEDES-BENZ C200, 1.5 AMG (A)   | Chassis No: | WDD2050772R481861 |
| Reg. Date:                  | 19/12/2019 (Man. Year: 2018)      | Odometer:   | 366212 km         |
| Colour:                     | White                             |             |                   |
| Engine Capacity:            | 1497 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 225/45 R18   | Rear Tyre Size:  | 225/45 R18   |
| Front Left Side:  | Hankook 6 mm | Rear Left Side:  | Hankook 6 mm |
| Front Right Side: | Hankook 6 mm | Rear Right Side: | Hankook 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 15,756.80         | 11,180.50         | 4,576.30          | 29.04         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 3,350.00          | 1,440.00          | 1,910.00          | 57.01         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>19,106.80</b>  | <b>12,620.50</b>  | <b>6,486.30</b>   | <b>33.95</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>10,000.00</b>  |                   |               |
| <b>Nett Amount (S\$)</b>                 | <b>19,106.80</b>  | <b>10,000.00</b>  | <b>9,106.80</b>   | <b>47.66</b>  |

INSPECTION

|                             |                          |                                                        |
|-----------------------------|--------------------------|--------------------------------------------------------|
| Date of Assignment:         | 26/08/2024               | TSL Auto Pro Selection Pte Ltd (HQ)                    |
| Date Inspected:             | 26/08/2024 Inspected At: | Blk 1 Kaki Bukit Avenue 6, #01-08 Autobay @ Kaki Bukit |
| Estimated Period of Repair: | 7.0 days                 | Singapore 417883                                       |

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                         | Deformed      | 1,674.00 FL | *1,674.00 FL |
| 2   | 1   |          | *FRONT BUMPER SIDE HOLDER             | Damaged       | 85.00 FL    | *85.00 FL    |
| 3   | 2   |          | *FRONT BUMPER SENSOR                  | Not Necessary | 550.00 FL   | *- FL        |
| 4   | 4   |          | *FRONT BUMPER SENSOR HOLDER           | Necessary     | 100.00 FL   | *100.00 FL   |
| 5   | 1   |          | *HEADLAMP                             | Cut           | 3,617.00 FL | *3,617.00 FL |
| 6   | 1   |          | *HEADLAMP LOWER BRACKET               | Not Necessary | 115.00 FL   | *- FL        |
| 7   | 1   |          | *HEADLAMP ECU                         | Not Necessary | 645.00 FL   | *- FL        |
| 8   | 1   |          | *FRONT FENDER                         | Dented        | 971.00 FL   | *971.00 FL   |
| 9   | 1   |          | *FRONT FENDER INNER SHIELD            | Torn          | 149.00 FL   | *149.00 FL   |
| 10  | 1   |          | *FRONT DOOR WING MIRROR               | Damaged       | 1,148.00 FL | *1,148.00 FL |
| 11  | 1   |          | *FRONT DOOR WING MIRROR GLASS         | Missing       | 842.00 FL   | *842.00 FL   |
| 12  | 1   |          | *FRONT DOOR WING MIRROR COVER         | Repair        | 145.00 FL   | *- FL        |
| 13  | 1   |          | *FRONT DOOR WING MIRROR SIGNAL LAMP   | Cracked       | 169.00 FL   | *169.00 FL   |
| 14  | 1   |          | *FRONT LOWER ARM                      | Bent          | 584.00 FL   | *584.00 FL   |
| 15  | 1   |          | *FRONT KNUCKLE ARM                    | Damaged       | 1,154.00 FL | *1,154.00 FL |
| 16  | 1   |          | *FRONT WHEEL HUB C/W BEARING          | Damaged       | 398.00 FL   | *398.00 FL   |
| 17  | 1   |          | *FRONT SHOCK ABSORBER                 | Not Necessary | 732.00 FL   | *- FL        |
| 18  | 1   |          | *FRONT CONTROL ARM                    | Not Necessary | 521.00 FL   | *- FL        |
| 19  | 1   |          | *FRONT UPPER ARM                      | Bent          | 754.00 FL   | *554.00 FL   |
| 20  | 1   |          | *ROCKER PANEL OUTER SKIRTING          | Not Necessary | 899.00 FL   | *- FL        |
| 21  | 1   |          | *SET FRONT BUMPER CLIPS               | Necessary     | 50.00 FS    | *50.00 FS    |
| 22  | 1   |          | *SET FRONT FENDER INNER SHIELD CLIPS  | Necessary     | 30.00 FS    | *30.00 FS    |
| 23  | 1   |          | *SET ROCKER PANE OUTER SKIRTING CLIPS | Not Necessary | 50.00 FS    | *- FS        |
| 24  | 1   |          | *FRONT WHEEL RIM                      | Cut           | 1,600.00 FS | *800.00 FS   |
| 25  | 1   |          | *FRONT TYRE                           | Not Necessary | 300.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                  |
|------------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                    | <b>17,282.00</b> | <b>12,325.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 1,525.20         | 1,144.50         |
| <b>Total Parts (\$\$)</b>                                  | <b>15,756.80</b> | <b>11,180.50</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                           | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                       |          |                 |                 |
| 1                              | PANEL BEATING, REMOVE AND REFIT PARTS | New      | 1,000.00        | 500.00          |
| 2                              | SPRAY PAINTING TO AFFECTED AREA       | New      | 1,200.00        | 600.00          |
| 3                              | WIRING CHECK                          | New      | 100.00          | 30.00           |
| 4                              | TO APPLY TUFF COAT                    | New      | 150.00          | 30.00           |
| 5                              | TO TRANSFER DOOR FITTINGS             | New      | 150.00          | 0.00            |
| 6                              | TO DISMANTLE FRONT UNDERCARRIAGE      | New      | 350.00          | 200.00          |
| 7                              | TO PERFORM DIAGNOSTIC TEST            | New      | 250.00          | 0.00            |
| 8                              | TO PERFORM WHEEL ALIGNMENT            | New      | 150.00          | 80.00           |
| <b>Gross Labour Cost (S\$)</b> |                                       |          | <b>3,350.00</b> | <b>1,440.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >