

# TSL AUTO PRO SELECTION PTE LTD

BLK 1 KAKI BUKIT AVE 6 #01-06 AUTOBAY @KAKI BUKIT  
SINGAPORE 417883

|               |                      |      |           |
|---------------|----------------------|------|-----------|
| TO            | : AIG                | DATE | 26/8/2024 |
| VEHICLE NO    | : SMR1169S (2019)    |      |           |
| VEHICLE MODEL | : MERCEDES BENZ C200 |      | Veron.    |
| CHASSIS NO    | : WDD2050772R481861  |      |           |

## CLAIM DETAILS: PARTS

|    | ITEMS                                             | QTY | UNIT PRICE  | TOTAL       |
|----|---------------------------------------------------|-----|-------------|-------------|
| 1  | FRONT BUMPER <i>Behind</i>                        | 1   | \$ 1,674.00 | \$ 1,674.00 |
| 2  | FRONT BUMPER SIDE HOLDER <i>and</i>               | 1   | \$ 85.00    | \$ 85.00    |
| 3  | FRONT BUMPER SENSOR <i>new</i>                    | 2   | \$ 275.00   | \$ 550.00   |
| 4  | FRONT BUMPER SENSOR HOLDER <i>new</i>             | 4   | \$ 25.00    | \$ 100.00   |
| 5  | HEADLAMP <i>cut</i>                               | 1   | \$ 3,617.00 | \$ 3,617.00 |
| 6  | HEADLAMP LOWER BRACKET <i>new</i>                 | 1   | \$ 115.00   | \$ 115.00   |
| 7  | HEADLAMP ECU <i>new</i>                           | 1   | \$ 645.00   | \$ 645.00   |
| 8  | FRONT FENDER <i>Dented</i>                        | 1   | \$ 971.00   | \$ 971.00   |
| 9  | FRONT FENDER INNER SHIELD <i>to be</i>            | 1   | \$ 149.00   | \$ 149.00   |
| 10 | FRONT DOOR WING MIRROR <i>Damaged</i>             | 1   | \$ 1,148.00 | \$ 1,148.00 |
| 11 | FRONT DOOR WING MIRROR GLASS <i>Mirror</i>        | 1   | \$ 842.00   | \$ 842.00   |
| 12 | FRONT DOOR WING MIRROR COVER <i>Repair</i>        | 1   | \$ 145.00   | \$ 145.00   |
| 13 | FRONT DOOR WING MIRROR SIGNAL LAMP <i>Cracked</i> | 1   | \$ 169.00   | \$ 169.00   |
| 14 | FRONT LOWER ARM <i>Beut</i>                       | 1   | \$ 584.00   | \$ 584.00   |
| 15 | FRONT KNUCKLE ARM <i>and</i>                      | 1   | \$ 1,154.00 | \$ 1,154.00 |
| 16 | FRONT WHEEL HUB C/W BEARING <i>and</i>            | 1   | \$ 398.00   | \$ 398.00   |
| 17 | FRONT SHOCK ABSORBER <i>new</i>                   | 1   | \$ 732.00   | \$ 732.00   |
| 18 | FRONT CONTROL ARM <i>new</i>                      | 1   | \$ 521.00   | \$ 521.00   |
| 19 | FRONT UPPER ARM <i>Beut</i>                       | 1   | \$ 754.00   | \$ 754.00   |
| 20 | ROCKER PANEL OUTER SKIRTING <i>new</i>            | 1   | \$ 899.00   | \$ 899.00   |

TOTAL PRICE: \$ 15,252.00

LESS 10% \$ 1,525.20

SUB TOTAL PRICE: \$ 13,726.80

## SPECIAL NETT ITEMS

|   | ITEMS                                      | QTY   | UNIT PRICE  | TOTAL       |
|---|--------------------------------------------|-------|-------------|-------------|
| 1 | FRONT BUMPER CLIPS <i>new</i>              | 1 SET | \$ 50.00    | \$ 50.00    |
| 2 | FRONT FENDER INNER SHIELD CLIPS <i>new</i> | 1 SET | \$ 30.00    | \$ 30.00    |
| 3 | ROCKER PANE OUTER SKIRTING CLIPS <i>nn</i> | 1 SET | \$ 50.00    | \$ 50.00    |
| 4 | FRONT WHEEL RIM <i>cut</i>                 | 1     | \$ 1,600.00 | \$ 1,600.00 |
| 5 | FRONT TYRE <i>new</i>                      | 1     | \$ 300.00   | \$ 300.00   |

TOTAL: \$ 2,030.00

## LABOUR

|   | JOB                                   | PRICE       | ADJUSTED COST | APPROVED |
|---|---------------------------------------|-------------|---------------|----------|
| 1 | PANEL BEATING, REMOVE AND REFIT PARTS | \$ 1,000.00 | 500           |          |
| 2 | SPRAY PAINTING TO AFFECTED AREA       | \$ 1,200.00 | 600           |          |
| 3 | WIRING CHECK                          | \$ 100.00   | 30            |          |

|   |                                  |           |      |  |
|---|----------------------------------|-----------|------|--|
| 4 | TO APPLY TUFF COAT               | \$ 150.00 | -20  |  |
| 5 | TO TRNASFER DOOR FITTINGS        | \$ 150.00 | X    |  |
| 6 | TO DISMANTLE FRONT UNDERCARRIAGE | \$ 350.00 | -200 |  |
| 7 | TO PERFORM DIAGNOSTIC TEST       | \$ 250.00 | X    |  |
| 8 | TO PERFORM WHEEL ALIGNMENT       | \$ 150.00 | -80  |  |

TOTAL: \$ 3,350.00

1440

#### ESTIMATE REPORT

TOTAL PARTS COST: \$ 15,756.80

TOTAL LABOUR COST: \$ 3,350.00

TOTAL REPAIR COST: \$ 19,106.80

total: 112620.50

L/s: 10K  
07 Days

10K

Can clear A10K

L/S

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: