

Estimate Repair For Vehicle FBK 3400 C (Yamaha FZN150)

QTY	DESCRIPTION OF PARTS		PRICE
1 pc	Handle bar / BT	\$	140.00
1 set	Handle bar balancer L/R / cut	\$	24.00
1 set	View mirror L.H / cut	\$	150.00
1 pc	Headlamp cover upper / BR	\$	58.00
1 pc	Front air guide cover L.H / cut	\$	58.00
1 pc	Front signal lamp L.H X	\$	38.00
1 pc	Front fender / cut	\$	185.00
1 pc	Front footrest L.H / cut	\$	45.00
1 pc	Gear shift pedal / BT	\$	65.00
1 pc	Rear mudguard / BR	\$	215.00
1 pc	Rear mudguard stay / BR	\$	30.00
1 pc	Rear mudguard reflector X	\$	12.00
1 pc	Rear tail lamp / cut	\$	150.00
1 pc	Rear tail cover X	\$	25.00
1-2 pcs	Rear signal lamp L/R \$ 38.00 (RH) / cut	\$	76.00
1 pc	Rear running chain guard / cut	\$	115.00
1 pc	Rear exhaust muffler protector (Black) / cut	\$	80.00
1 pc	Rear exhaust muffler protector (Silver) / cut	\$	55.00
		\$	1,521.00
	Less 10%	\$	152.10
		\$	1,368.90
	<u>S/NETT ITEM</u>		
1 set	Engine crash bar L/R / BT / cut	\$	340.00
1 set	Front & rear number plate / BT	\$	35.00
1 pc	Rear box bracket X R	\$	280.00
		\$	2,023.90
	<u>Labour charge</u>		
1]	Transportation (2 Trips)	\$	80.00 60
2]	Front fork & steering stem alignment.	\$	180.00 150
3]	Replace, realign & adjust above damaged parts. check wiring, re-connection & lighting system.	\$	350.00 300
	<b>Sub Total :</b>	\$	<b>610.00</b>

Steve (LKK)

28/8/24, 10.30am

in it

L/S

by AC Y

3 days

Jim's rep 2K

**Total Parts and Labour \$ 2,633.90**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: