

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

not Authorized
for
work
26/8/24
2/s # 4300
4 days.

VEHICLE No: SLM 8500K

1PC	BONNET		R	\$1,422.10 X
1PC	FRONT BUMPER	764.30	DU	\$1,220.10 ✓
1PC	FRONT BUMPER CENTRE GRILLE		11	\$221.10 X
2PCS	FRONT BUMPER SIDE RETAINERS @\$35.00		11	\$70.00 X
1SET	FRONT BUMPER CLIPS		11	\$45.00 ✓
1PC	FRONT BUMPER BEAM	288.80	11	\$322.10 ✓
1PC	FRONT GRILLE		11	\$645.10 X
1PC	FRONT FOG LAMP N/S	366.50	11	\$390.00 ✓
1PC	FRONT FOG LAMP GARNISH N/S		11	\$185.00 ✓
1PC	FRONT BUMPER LOWER GARNISH N/S	290.00	11	\$338.20 ✓
1PC	FRONT BUMPER LOWER UNDER COVER		11	\$455.20 X
2PCS	FRONT BUMPER PDC SENSORS @\$210.00		11	\$420.00 X
1PC	HEADLAMP N/S	2866.30	11	\$3,200.00 ✓
1PC	HEADLAMP LOWER BRACKET N/S	86.50	11	\$150.00 ✓
1PC	FRONT SUPPORT PANEL		11	\$620.80 X
1PC	FRONT FENDER N/S		11	\$1,640.00 X
1PC	FRONT FENDER INNER SHIELD N/S	175.40	11	\$188.90 ✓
1PC	AIR RESONATOR BOX ASSY		11	\$298.50 ✓
1PC	FRONT SPORT RIM N/S		11	\$880.00 X
1PC	FRONT KNUCKLE ARM N/S		11	\$450.00 X
1PC	FRONT KNUCKLE BEARING N/S		11	\$250.00 X
				\$12,712.10
				LESS 20% \$10,169.68

TO CHECK WIRING	\$100.00 20
TO DISMANTLE & REPLACED FRONT PDC SENSOR	11 \$80.00 X
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	11 \$500.00 X
TO CONDUCT WHEEL ALIGNMENT	\$100.00 60
TO SPRAY RUST PROOFING	11 \$100.00 X
TO REFILL AIR CON GAS	11 \$100.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,000.00 500
TO PUTTY & SPRAY PAINTING	\$1,500.00 800
TOTAL	\$13,649.68

LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) before survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-5066
202
4052.80
1380
5432.8
202
4346