

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37-SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 18-Jun-24

Estimate no.

1409

Plate No. FBR53D

Model. XMAX300

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	REAR SPORT RIM <i>cut 1/2</i>	550.00	✓	
2	REAR DISC BRAKE <i>1 n</i>	280.00	X	
3	REAR SUSPENSION <i>1 n</i>	700.00	X	
4	EXHAUST PROTECTOR <i>cut 1/2</i>	220.00	X	
5	EXHAUST CAP <i>1 n</i>	180.00	X	
6	REAR FAIRING COVER L <i>cut</i>	380.00	✓	
7	MAINSTAND <i>cut</i>	280.00	✓	
8	SIDE STAND <i>2</i>	180.00	X	
9	FRONT FAIRING COVER L <i>cut</i>	350.00	✓	
10	FRONT FAIRING PANEL COVER L <i>cut \$190</i>	280.00	✓	
11	FOOTREST BOARD L <i>cut n</i>	200.00	X	
12	FOOTREST BOARD UNDER L <i>cut \$175</i>	180.00	✓	
13	EXHAUST PIPE <i>1 n</i>	2,200.00	X	
14	LABOUR	500.00	280	

*not allowed
run n 90096608
noisy
19/6/24*

*3 days
warranty*

*P-1928
102
1732.50
280
2012.50*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 10% \$ 648.00
\$ 6,480.00
Sub Total : \$ 5,832.00
GST 9% \$ 524.88
Total: \$ 6,356.88

Estimate given are base on visible damages ONLY before dismantling of the vehicle

Acknowledged by Repairer

This is computer generated no signature is required.

Signature:

Date: