



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080442/Unh3
75 BRAS BASAH ROAD	Date:	03/09/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YQ 2404U	Veh. Inspected	SNB 8144P
Policy No.	-	Coverage	0
Claim No.	MT/1292390-002	Excess	\$0.00
Assign From	SERENE LIM	Assign Date	27/08/2024

2. Vehicle Details

Make & Model	TOYOTA HARRIER G GRADE (A)	C.C	1998
Engine No.	8ARZ097552	Year of Reg.	02/07/2019
Chassis No.	JTEKB3GH80J000771	Colour	PURPLE
Odometer	98203 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/55R18	MICHELIN	6
L/H Front Tyre	235/55R18	MICHELIN	6
R/H Rear Tyre	235/55R18	MICHELIN	6
L/H Rear Tyre	235/55R18	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/08/2024	Inspection Date	27/08/2024 (12:22)
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days