

LEE BROTHERS AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

INCOME INSURANCE LIMITED

75 BRAS BASAH ROAD

SINGAPORE 189557

YQ2404U

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

VEHICLE NO : SNB8144P
MAKE/MODEL : TOYOTA HARRIER
ACC DATE : 23.08.2024

PARTICULAR

UNIT PRICE

AMOUNT

QTY

SS

SS

LIST PRICE

1	1	REAR BUMPER	904.33	cur/70m	904.33	✓
2	2	REAR BUMPER SIDE RETAINERS -R/L	220.50	17	441.00	X
3	1	REAR FENDER -LH	1,245.89	10/100m	1,245.89	✓
4	1	REAR FENDER INNER SHIELD	141.75	17	141.75	X
5	1	REAR FENDER 1/4 GLASS MOULDING	841.72	nee	841.72	✓
6	1	REAR FUEL LID	145.12	17	145.12	X
7	1	REAR TAILLAMP -LH	990.34	Bro	990.34	✓
8	1	REAR TAILLAMP PANEL	291.55	17	291.55	X
9	1	REAR TAILLAMP CLIP	18.60	17	18.60	X
					5,020.30	
			LESS 25%		1,255.08	

3,765.23

SPECIAL NETT ITEMS

1	1	(SET) REAR BUMPER CLIP	50.00	nee	50.00	30
2	1	(SET) REAR FENDER GLASS SEALANT	60.00	nee	60.00	30
3	2	REAR FUEL LID REVERT PLUG	15.00	nee	30.00	✓
					140.00	

LABOUR CHARGES:

1	TO CHECK REAR ELECTRICAL WIRING	40.00	20
2	TO REMOVE AND REFIX REAR INTERIOR TRIMS	120.00	60
3	TO REMOVE AND REFIX REAR FENDER GLASS	180.00	100
4	TO TUFF KOTE	60.00	30
5	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	1,200.00	750
6	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGE PARTS	900.00	600
TOTAL:		2,500.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 6,405.23

not Acknowled
27/8/24
morris
1/s #3700
OK chg.
Take photo after 127

2-3982-28
283
2986.71
90
1560
4636.71
3709