

# JC Motor Consultancy

UEN No: 53383584D // Email: jcmotorconsultancy@gmail.com

Not Authorized  
27/8/24  
1/5 to 8000/  
Wright, Henry  
8 days

Vehicle number: SKA8416X

Vehicle Made & Model: TOYOTA ALTIS

| Qty | List Items                                                  | Amount \$           |
|-----|-------------------------------------------------------------|---------------------|
| 1   | Front bumper <i>20/10.1</i>                                 | 769.60 ✓            |
| 1   | Front bumper logo <i>rec</i>                                | 89.95 ✓             |
| 1   | Front bumper logo grille <i>11</i>                          | 181.20 X            |
| 1   | Front bumper top seal <i>111</i>                            | 89.60 ✓             |
| 1   | Front bumper sponge <i>11</i>                               | 140.63 X            |
| 1   | Front bumper reinforcement <i>3uf</i>                       | 515.60 ✓            |
| 1   | Front bumper fog lamp - LH <i>Cne</i>                       | 361.55 ✓            |
| 1   | Front bumper fog lamp cover <i>Torn</i>                     | 110.25 ✓            |
| 1   | Front fender - LH <i>R</i>                                  | 781.66 X            |
| 1   | Front grille assy <i>11</i>                                 | 631.52 X            |
| 2   | Front headlamps - L/R @ 1260.50 <i>M/S holder cne 2/511</i> | 2,521.00 <i>12C</i> |
| 1   | Front support panel <i>R</i>                                | 991.60 X            |
| 1   | Front brace panel <i>11</i>                                 | 110.45 X            |
| 1   | Air con condenser <i>11</i>                                 | 1,011.35 X          |
| 1   | Air cleaner intake duct <i>11</i>                           | 241.50 X            |
| 1   | Air cleaner resonator <i>11</i>                             | 310.60 X            |
| 1   | Horn <i>11</i>                                              | 86.60 X             |
| 1   | Rear boot lid <i>R</i>                                      | 1,053.60 X          |
| 1   | Rear boot logo <i>11</i>                                    | 89.95 X             |
| 1   | Rear boot chrome moulding <i>11</i>                         | 299.61 X            |
| 2   | Rear boot lamps - L/R @ 231.60 <i>N/S 110/5320</i>          | 463.20 <i>WC</i>    |
| 1   | Rear boot inner lock <i>11</i>                              | 281.63 X            |
| 1   | Rear boot w/strip <i>11</i>                                 | 261.92 X            |
| 1   | Rear bumper <i>Torn</i>                                     | 799.60 ✓            |
| 1   | Rear bumper reflector <i>M/S</i>                            | 89.95 ✓             |
| 1   | Rear bumper bracket - RH <i>2uf</i>                         | 110.25 ✓            |
| 1   | Rear bumper foam <i>11</i>                                  | 160.93 X            |
| 2   | Rear bumper side retainers - L/R @ 115.20 <i>2/5cne</i>     | 230.40 <i>12C</i>   |
| 1   | Rear bumper side bracket - RH <i>Cne</i>                    | 89.55 ✓             |
| 1   | Rear end panel <i>Body 20</i>                               | 781.10 ✓            |
| 1   | Rear end pannel garnish <i>11</i>                           | 211.43 X            |
| 1   | Rear exhaust silencer <i>20/3uf</i>                         | 822.62 ✓            |
| 1   | Rear exhaust insulator <i>11</i>                            | 130.20 X            |

Vehicle number: SKA8416X

Vehicle Made & Model: TOYOTA ALTIS

|                   |                                  |      |                  |   |
|-------------------|----------------------------------|------|------------------|---|
| 1                 | Rear exhaust mountings @ 28.60   | Torn | 57.20            | ✓ |
| 1                 | Rear exhaust pipe - CTR          | 11   | 1,055.90         | X |
| 1                 | Rear fender - RH                 | 6.00 | 1,257.60         | ✓ |
| 1                 | Rear fender inner shield - RH    | Torn | 114.71           | ✓ |
| 1                 | Rear fender air vent             | 121  | 121.63           | ✓ |
| 1                 | Rear fender inner trim           | 17   | 481.66           | X |
| 1                 | Rear taillamp - RH               | 320  | 561.21           | ✓ |
| 1                 | Rear taillamp panel - RH         | R    | 299.61           | X |
| 1                 | Rear taillamp lower bracket - RH | 17   | 86.50            | X |
| 1                 | Rear windscreen moulding         | 122  | 126.30           | ✓ |
| 1                 | Side sill panel garnish - RH     | 122  | 581.90           | X |
| <b>Sub-total</b>  |                                  |      | <b>19,564.82</b> |   |
| <b>Less 25%</b>   |                                  |      | <b>4,891.21</b>  |   |
| <b>Total List</b> |                                  |      | <b>14,673.62</b> |   |

#### Special Nett Items

|                           |                                |     |               |    |
|---------------------------|--------------------------------|-----|---------------|----|
| 1 set                     | Front bumper clip              | 122 | 60.00         | 30 |
| 1 set                     | Front number plate with holder | 321 | 65.00         | 40 |
| 1 set                     | Rear bumper clip               | 122 | 60.00         | 30 |
| 1                         | Rear reverse sensor            | 17  | 280.00        | X  |
| 1 set                     | Rear windscreen sealant        | 122 | 80.00         | 40 |
| <b>Total Special Nett</b> |                                |     | <b>545.00</b> |    |

#### Labour charges

|                                                          |          |      |
|----------------------------------------------------------|----------|------|
| To check front/ rear electrical wiring                   | 80.00    | 20   |
| To remove, refix rear interior trims to assist repair    | 120.00   | 60   |
| To remove, refix rear winscreen                          | 180.00   | 120  |
| To remove, refix rear reverse sensor                     | 60.00    | 30   |
| To remove, refix rear exhaust                            | 120.00   | 60   |
| To remove, refix A/C condenser & refull A/C gas          | 180.00   | X    |
| To respray undercoating                                  | 150.00   | 60   |
| To respray painting and etc.                             | 1,800.00 | 1600 |
| Panel beating, cut, weld, remove & replacing above parts | 2,000.00 | 1580 |

**Total Labour** 4,690.00

**ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 19,908.62**

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-8475-57  
252  
638668  
140  
3530  
1002668  
202  
80M