

LEE BROTHERS AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

INCOME INSURANCE LIMITED

75 BRAS BASAH ROAD

SINGAPORE 189557

SNA8739D

ESTIMATE

VEHICLE NO : SMR8536U
MAKE/MODEL : TOYOTA SIENTA
ACC DATE : 23.08.2024

Not Authorized
mean
27/8/24
1/5 # 4100
Teleph. After 12
5 days

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
	<u>LIST PRICE</u>		
1	1 REAR TAILGATE	1,602.41	1,602.41 ✓
2	1 REAR TAILGATE GLASS MOUDLING	121.95	121.95 ✓
3	1 REAR TAILGATE LOGO	89.95	89.95 ✓
4	1 REAR TAILGATE EMBLEM HYBIRD	86.50	86.50 ✓
5	1 REAR TAILGATE OUTER GARNISH	371.25	371.25 X
6	2 REAR TAILGATE LAMP RH/LH	481.20	962.40 X
7	1 REAR TAILGATE INNER LOCK	566.01	566.01 ✓
8	1 REAR TAILGATE INNER TRIM	410.50	410.50 X
9	1 REAR TAILGATE WEATHERSTRIP	411.02	411.02 X
10	2 REAR TAILGATE STOPPER RH/LH	18.60	37.20 X
11	2 REAR TAILGATE DAMPER RH/LH	195.60	391.20 X
12	2 REAR TAILLAMP RH/LH	581.60	1,163.20 X
13	1 REAR BUMPER	641.50	641.50 ✓
14	1 REAR BUNPER CENTER PAD	372.45	372.45 ✓
15	2 REAR BUMPER SIDE PAD RH/LH	281.65	563.30 X
16	2 REAR BUMPER REFLECTOR	89.95	179.90 X
17	2 REAR BUMPER TOP HOLDER RH/LH	89.55	179.10 X
18	2 REAR BUMPER SIDE RETAINER RH/LH	91.50	183.00 X
19	1 REAR END PANEL	781.60	781.60 ✓
20	1 REAR END PANEL GARNISH	261.33	261.33 ✓
21	1 REAR SMART KEYLESS SENSOR	191.20	191.20 X
			9,566.97
		LESS 25%	2,391.74
			7,175.23

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LEE BROTHERS AUTOMOTIVE PTE.LTD

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
<u>SPECIAL NETT ITEMS</u>			
1	1 (SET) REAR TAILGATE GLASS SEALANT <i>neu</i>		80.00 <i>40</i>
2	1 (SET) REAR TAILGATE INNER TRIM CLIP <i>neu</i>		65.00 <i>30</i>
3	1 (SET) REAR BUMPER CLIP <i>neu</i>		50.00 <i>30</i>
4	1 (SET) REAR REVERSE SENSOR <i>neu</i>		280.00 <i>X</i>
5	1 REAR REVERSE CAMERA <i>neu</i>		480.00 <i>X</i>
			955.00

<u>LABOUR CHARGES :</u>			
1	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS		1,200.00 <i>600</i>
2	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		1,080.00 <i>800</i>
3	TO REMOVE AND REFIX REAR WINDSCREEN		180.00 <i>120</i>
4	TO TRANSFER REAR TAILGATE PARTS		150.00 <i>60</i>
5	TO CHECK REAR WIRING		50.00 <i>20</i>
6	TO REMOVE AND REFIX REAR INNER TRIM		120.00 <i>60</i>
7	TO REMOVE AND REPLACE REAR REVERSE SENSOR AND CAMERA		60.00 <i>30</i>
8	TO TUFF KOTE		100.00 <i>50</i>
TOTAL:			2,940.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 11,070.23

P- 4383.90
252

3287.93
100

1740

5127.93
222

4102.