

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2401904
INV Date : 18-12-2024

Reference CD/FCI24080447/Kma3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SNM 7965K
Insured Veh. SHC 1871K
Claim No. D24007490MFCT/CTPL/CL/TPD
Policy No. D-24101861MFCT
Accident Date 25/08/2024
Inspection Date 29/08/2024

Description	Amount
Third Party Express Settlement	300.00
Sub-Total	300.00
GST (9%)	27.00
Grand Total	327.00

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CD/FCI24080447/Kma3q2
16 RAFFLES QUAY	Date:	18/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHC 1871K	Veh. Inspected	SNM 7965K
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24007490MFCT/CTPL/CL/TPD	Excess	\$0.00
Assign From	CHRIS LIM	Assign Date	27/08/2024

2. Vehicle Details

Make & Model	AUDI A3 SPORTBACK 1.0 TFSI S TRONIC (LED)	C.C	999
Engine No.	CHZC22346	Year of Reg.	09/11/2018
Chassis No.	WAUZZZ8V2JA153571	Colour	METALLIC LIGHT GREY
Odometer	61507 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/40R18	GOODYEAR	7
L/H Front Tyre	225/40R18	GOODYEAR	7
R/H Rear Tyre	225/40R18	GOODYEAR	7
L/H Rear Tyre	225/40R18	GOODYEAR	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S DOOR MIRROR.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/08/2024	Inspection Date	29/08/2024
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNM 7965K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT N/S DOOR GLASS	CUT	\$180.00	\$180.00
1	FRONT N/S DOOR MIRROR ASSY	DENTED	\$780.00	\$780.00
1	FRONT N/S DOOR MIRROR LAMP	CRACKED	\$75.00	\$75.00
1	FRONT N/S DOOR MIRROR COVER	MTG CRACKED	\$130.00	\$130.00
1	FRONT N/S DOOR MIRROR CASING	CUT	\$80.00	\$80.00
1	FRONT N/S DOOR MIRROR GLASS	CRACKED	\$790.00	\$790.00
1	FRONT N/S DOOR OUTER MOULDING	SERVICEABLE	\$190.00	\$0.00
	LESS 10.00% DISCOUNT		(\$222.50)	(\$203.50)
			\$2,002.50	\$1,831.50
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRT N/S DOOR GLASS SOLAR FILM (SN)	NECESSARY	\$80.00	\$60.00
			\$80.00	\$60.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY REPLACED PARTS		\$300.00	\$80.00
	TO REMOVE DOOR BOARD FOR RENEW DOOR MIRROR AND DOOR BELT DOOR GLASS		\$250.00	\$150.00
			\$550.00	\$230.00
GRAND TOTAL			\$2,632.50	\$2,121.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,700.00
Report Ref No: CD/FCI24080447/Kma3q2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.


PHOTOGRAPHS FOR VEHICLE NO. : SNM 7965K




PHOTOGRAPHS FOR VEHICLE NO. : SNM 7965K



PHOTOGRAPHS FOR VEHICLE NO. : SNM 7965K



PHOTOGRAPHS FOR VEHICLE NO. : SNM 7965K



PHOTOGRAPHS FOR VEHICLE NO. : SNM 7965K





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SNM 7965K

