

ASS. REC. BY:

REF:

F02/24080447/Kmas

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNM 7965K Yr Regn: 11, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3 TFSI c.c. 999

Colour

M.L. Grey A/C: Insured / Std / NI / NA

Sp. Reading

61507 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU 888 8V2JA 153571

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

25/8/12

D.O.I.

29/8/2024

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

M LH door mirror

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/9 2124 81700d Caku

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07146

Date : 26-Aug-2024

PAGE : 1

Vehicle Insured : SHC1871K
Accident Date : 25-Aug-2024

Our Ref : 024167 (FIRST) / CHAN

TONG JIN SHI JULIA
464B CLEMENTI AVE 1
#12-48
Singapore 122464

*NOT Withheld
L1Pm @ 1700h
Re survey After Rainy
2 days*

ESTIMATED COST OF REPAIR FOR AUDI A3 SNM7965K

1 pc	Front n/s door glass	WT CM 180.00	—
1 pc	Front n/s door mirror assy	Ref 780.00	—
1 pc	Front n/s door mirror lamp	CM 75.00	—
1 pc	Front n/s door mirror cover	mycm 130.00	✓
1 pc	Front n/s door mirror casing	WT 80.00	✓
1 pc	Front n/s door mirror glass	CM 790.00	—
1 pc	Front n/s door outer moulding	Pr 190.00	X
		2,225.00	
Less 10% :		222.50	

1 pc Frt n/s door glass solar film

To putty and spray replaced parts

To remove door board for renew door mirror and door belt, door glass

2,002.50 *Car*
80.00 *sn*

300.00 *sd*

250.00 *150*

Total : S\$ 2,632.50

Singapore Dollars Two Thousand Six Hundred and Thirty Two and Cents Fifty Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: