



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080448/Aqh3e2
75 BRAS BASAH ROAD	Date:	20/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKA 8416X	<b>Veh. Inspected</b>	SNR 657U
<b>Policy No.</b>	-	<b>Coverage</b>	0
<b>Claim No.</b>	MT/1292348-002	<b>Excess</b>	\$0.00
<b>Assign From</b>	ENG HUEY HUEY	<b>Assign Date</b>	27/08/2024

### 2. Vehicle Details

<b>Make &amp; Model</b>	TOYOTA NOAH HYBRID	<b>C.C</b>	1797
<b>Engine No.</b>	2ZR2Z06287	<b>Year of Reg.</b>	24/05/2024
<b>Chassis No.</b>	ZWR900160518	<b>Colour</b>	WHITE
<b>Odometer</b>	10031 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>General</b>	GOOD
<b>Modification(s)</b>	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
<b>R/H Front Tyre</b>	205/55 R17	TOYO	6
<b>L/H Front Tyre</b>	205/55 R17	TOYO	6
<b>R/H Rear Tyre</b>	205/55 R17	TOYO	6
<b>L/H Rear Tyre</b>	205/55 R17	TOYO	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	25/08/2024	<b>Inspection Date</b>	27/08/2024 (16:00)
<b>Survey held at</b>	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days