


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 26.08.2024

ZWR900160518

Xiao Chan.

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNR657U**
MODEL : **TOYOTA NOAH**
DATE OF ACCIDENT : 25.08.2024
TIME OF ACCIDENT : 10:05 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Delint</i>	1	\$ 2,292.80	\$ 2,292.80
2	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 128.20	\$ 256.40
3	REAR BUMPER REFLECTOR COVER GARNISH <i>cut RA</i>	2	\$ 78.00	\$ 156.00
4	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 183.50	\$ 367.00
5	TAILGATE <i>Delint</i>	1	\$ 2,691.50	\$ 2,691.50
6	TAILGATE DAMPER (ELECTRIC) <i>new</i>	2	\$ 468.20	\$ 936.40
7	TAILGATE OUTER GARNISH <i>new</i>	1	\$ 777.80	\$ 777.80
8	TAIL GATE LOGO <i>new</i>	1	\$ 96.80	\$ 96.80
9	TAIL GATE EMBLEM 'HYBRID SYNERGY DRIVE' <i>new</i>	1	\$ 98.60	\$ 98.60
10	TAIL GATE EMBLEM 'NOAH' <i>new</i>	2	\$ 198.20	\$ 396.40
11	TAILGATE STOPPER <i>new</i>	2	\$ 39.50	\$ 79.00
12	TAILGATE INNER LOCK <i>Delint</i>	1	\$ 685.30	\$ 685.30
13	TAILGATE LOWER LOCK <i>new</i>	1	\$ 65.20	\$ 65.20
14	TAILGATE BUZZER <i>new</i>	1	\$ 272.60	\$ 272.60
15	TAILGATE DETECTOR <i>cut</i>	1	\$ 198.60	\$ 198.60
16	TAILGATE DETECTOR WIRE HARNESS <i>lt</i>	1	\$ 287.10	\$ 287.10
17	TAILGATE INNER TRIM <i>cut</i>	1	\$ 923.10	\$ 923.10
18	TAILGATE INNER HOLDER <i>new</i>	1	\$ 50.60	\$ 50.60
19	TAILGATE WEATHER STRIP <i>lt</i>	1	\$ 452.80	\$ 452.80
20	TAILGATE WINDSCREEN GLASS C/W MOULDING <i>new</i>	1	\$ 2,143.80	\$ 2,143.80
21	TAIL LAMP <i>new</i>	2	\$ 1,048.30	\$ 2,096.60

1389
+
78
+
1985
+
+
+
-
85
+
515
+
+
-
852
+
185285
+

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNR657U**
 MODEL : **TOYOTA NOAH**
 DATE OF ACCIDENT : 25.08.2024
 TIME OF ACCIDENT : 10:05 HOURS

22	TAIL LAMP LOWER GARNISH <i>RH form</i>	2	\$ 262.50	\$ 525.00
23	TAIL LAMP LOWER GARNISH RETAINER <i>new</i>	2	\$ 218.50	\$ 437.00
24	TAIL LAMP LOWER PANEL <i>new</i>	2	\$ 354.60	\$ 709.20
25	REAR FENDER INNER TRIM <i>RH covered</i>	2	\$ 1,052.80	\$ 2,105.60
26	REAR FENDER COWLING <i>new</i>	2	\$ 341.80	\$ 683.60
27	REAR AIR CON BLOWER MOTOR <i>new</i>	1	\$ 3,694.00	\$ 3,694.00
28	REAR END PANEL C/W END EXTEND PANEL <i>new</i>	1	\$ 1,169.90	\$ 1,169.90
29	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 465.20	\$ 465.20
30	REAR FLOOR MAT <i>new</i>	1	\$ 1,046.50	\$ 1,046.50
31	REAR FLOOR PANEL TOP BOARD <i>covered</i>	1	\$ 1,468.20	\$ 1,468.20
32	REAR FLOOR PANEL TOP BOARD INNER SUPPORT <i>new</i>	1	\$ 473.50	\$ 473.50
33	REAR JACK COVER GARNISH <i>Deland</i>	1	\$ 185.00	\$ 185.00
34	REAR BLIND SPOT SENSOR RH <i>new</i>	1	\$ 1,865.30	\$ 1,865.30
35	REVERSE SENSOR <i>Deland</i>	2	\$ 575.50	\$ 1,151.00
36	REVERSE SENSOR HOLDER <i>new</i>	4	\$ 69.50	\$ 278.00
37	REVERSE SENSOR WIRE HARNESS <i>Deland</i>	1	\$ 385.60	\$ 385.60

9387.60
7040.70

TOTAL PRICE \$ 31,967.00
 LESS 25% \$ 7,991.75
 SUB TOTAL PRICE \$ 23,975.25

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
4	TAIL LAMP LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
6	TAILGATE OUTER GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
7	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
8	TAILGATE TOP INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
9	TAILGATE SIDE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
11	TAILGATE WINDSCREEN SEALANT <i>Deland</i>	1	\$ 80.00	\$ 80.00
12	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
13	TAILGATE WINDSCREEN SOLAR FILM <i>new</i>	1	\$ 550.00	\$ 550.00
14	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00

262.50
+
890
+
1052.80
+
349
+
885
+
480
+
+
30
+
10
+
30
+
40
+
30
+
30

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNR657U**
 MODEL : **TOYOTA NOAH**
 DATE OF ACCIDENT : 25.08.2024
 TIME OF ACCIDENT : 10:05 HOURS

15	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
16	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	<i>-20</i>
17	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+60</i>

250 TOTAL \$ 1,540.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	<i>800</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>900</i>
3	TUFF COAT	\$ 250.00	<i>80</i>
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 180.00	<i>80</i>
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>+</i>
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 150.00	<i>120</i>
9	TRANSFER TAILGATE MECHANISM	\$ 120.00	<i>80</i>
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>+</i>
11	REMOVE AND REFIX REAR VIDEO CAM	\$ 80.00	<i>50</i>
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>X</i>

7210

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNR657U**
MODEL : **TOYOTA NOAH**
DATE OF ACCIDENT : 25.08.2024
TIME OF ACCIDENT : 10:05 HOURS

	TOTAL	\$ 4,670.00
TOTAL PARTS COST	: \$	25,515.25
TOTAL LABOUR COST	: \$	4,670.00
TOTAL REPAIR COST	: \$	30,185.25

Adnan L
2/s 27/08/24
06hys

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 9500.70
H/s: 7.6K

7.6K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: