

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SLG6771P

Make & Model: Hyundai Accent

Chassis number: KMHCT41BTHU214070

No.	Description of spare parts	Qty	Amount S\$
1	Bootlid <i>Exe Buebird</i>	1	\$ 1,389.00
2	Bootlid centre emblem <i>3pc</i>	1	\$ 33.00
3	Bootlid "Accent" emblem	1	\$ 36.00
4	Bootlid lock <i>new</i>	1	\$ 143.00
5	Bootlid RH hinge <i>3pc</i>	1	\$ 119.00
6	Bootlid LH hinge <i>3pc</i>	1	\$ 119.00
7	Bootlid weatherstrip <i>3pc</i>	1	\$ 101.00
8	Bootlid inner trim clips	1set	\$ 70.00
9	Rear bumper <i>Del-d</i>	1	\$ 546.00
10	Rear bumper clips <i>new</i>	1set	\$ -70.00
11	Rear bumper reinforcement <i>new</i>	1	\$ 344.00
12	Rear bumper RH side retainer <i>new</i>	1	\$ 46.00
13	Rear bumper LH side retainer <i>new</i>	1	\$ 46.00
14	Rear bumper LH reflector <i>new</i>	1	\$ 58.00
15	Rear bumper LH side reverse sensor <i>new</i>	1	\$ 248.00
16	Rear bumper LH centre reverse sensor <i>new</i>	1	\$ 248.00
17	Rear bumper reverse sensor wire harness <i>new</i>	1	\$ 368.00
18	End panel <i>Del-d</i>	1	\$ 578.00
19	End panel inner garnish <i>Del-d</i>	1	\$ 118.00
20	End panel inner garnish clips <i>new</i>	1set	\$ -50.00
21	Rear fender LH inner trim <i>new</i>	1	\$ 202.00
22	Rear fender LH inner trim clips <i>new</i>	1set	\$ 60.00
23	Rear fender LH splash shield <i>3pc</i>	1	\$ 93.00
24	Rear fender LH splash shield clips <i>3pc</i>	1set	\$ 40.00
25	Spare tyre panel upper board <i>new</i>	1	\$ 299.00
26	LH taillamp assy <i>new</i>	1	\$ 414.00
27	LH taillamp panel <i>new</i>	1	\$ 72.00
28	LH taillamp lock clips <i>3pc</i>	1set	\$ 21.00
29	LH taillamp gasket <i>3pc</i>	1	\$ 27.00

\$ 5,958.00

Parts less 20% \$ 1,191.60

Total: \$ 4,766.40

No.	Special Nett Items	Qty	Amount S\$
1	End panel joint sealant <i>new</i>	1	\$ 70.00

Total: \$ 70.00

No.	Labour and painting	Amount S\$

1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,400.00	700
2	Spray painting on affected areas and panels	\$ 1,200.00	700
3	Check wiring and lighting system on affected areas	\$ 60.00	30
4	Apply rust coating chemical on affected areas and panels	\$ 80.00	60
5	Remove and replace bootlid inner mechanism to new bootlid	\$ 120.00	60
6	Remove and replace rear bumper reverse sensors to assist repair	\$ 80.00	50
7	Remove and replace rear inner trims, garnish and covers to assist repair	\$ 320.00	60

Total: \$ 3,260.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Adrian C
2/s 27/08/24
66 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____