



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TAN SOON HENG @ABDULLAH HALIM
BLK 448 YISHUN RING ROAD #07-74
SINGAPORE 760448

Contact : 88332686

TP 111
Xiao Tong

TAX INVOICE

Repair Code : CLM18357

Date in : 30/07/2024

Vehicle Num. : SGF8322D

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11109733/L15B4029736

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>Debed</i>	1	910.20	✓ 910.20
FRONT RH DOOR BLACK TAPE <i>new</i>	1	26.40	✓ 26.40
FRONT RH DOOR GLASS OUTER MOULDING <i>fixe n</i>	1	28.60	✓ 28.60
FRONT RH DOOR MECHANISM LOCK	1	221.70	✓ 221.70
REAR LH FENDER <i>new</i>	1	790.20	✓ 790.20
REAR LH FENDER ARCH GARNISH <i>lit</i>	1	195.00	✓ 195.00
REAR RH DOOR <i>Debed</i>	1	883.40	✓ 883.40
REAR RH DOOR BLACK TAPE <i>new</i>	1	29.80	✓ 29.80
REAR RH DOOR CHECKER <i>new</i>	1	50.40	✓ 50.40
REAR RH DOOR GLASS OUTER MOULDING <i>new</i>	1	30.40	✓ 30.40
REAR RH DOOR GLASS REGULATOR WITH MOTOR <i>new</i>	1	412.50	✓ 412.50
REAR RH DOOR HINGE (LOWER) <i>fixe n</i>	1	49.20	✓ 49.20
REAR RH DOOR HINGE (TOP)	1	49.20	✓ 49.20
REAR RH DOOR INNER TRIM BOARD <i>new</i>	1	499.80	✓ 499.80
REAR RH DOOR LOCK STRIKER <i>new</i>	1	39.80	✓ 39.80
REAR RH DOOR MECHANISM LOCK <i>new</i>	1	299.70	✓ 299.70
REAR RH DOOR OUTER HANDLE <i>fixe n</i>	1	93.70	✓ 93.70
REAR RH DOOR WEATHER STRIP <i>fixe n</i>	1	149.20	✓ 149.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN SOON HENG @ABDULLAH HALIM
 BLK 448 YISHUN RING ROAD #07-74
 SINGAPORE 760448

Contact : 88332686

TAX INVOICE

Repair Code : CLM18357

Date in : 30/07/2024

Vehicle Num. : SGF8322D

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11109733/L15B4029736

REAR RH DOOR WEATHER STRIP (LOWER)	1	2883.70	29.20	X	29.20
REAR RH DOOR WEATHER STRIP (VERTICAL)	1		39.40	X	39.40
ROCKER GARNISH RH	1	2306.96	471.90	X	471.90
Subtotal before discount					5,299.70
Percentage discount 20%					1,059.94
Sub-total 1					4,239.76
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	1		50.00	X	50.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	1		50.00	30	50.00
REAR RH FENDER ARCH GARNISH CLIPS - SET	1	60	30.00	X	30.00
ROCKER GARNISH RH CLIPS - SET	1		50.00	X	50.00
Subtotal before discount					180.00
Percentage discount 0%					0.00
Sub-total 2					180.00
Parts-total					4,419.76

LABOUR

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	X	80.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	120	140.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	600	1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	400	1,200.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN SOON HENG @ABDULLAH HALIM
 BLK 448 YISHUN RING ROAD #07-74
 SINGAPORE 760448

Contact : 88332686

TAX INVOICE

Repair Code : CLM18357

Date in : 30/07/2024

Vehicle Num. : SGF8322D

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11109733/L15B4029736

To apply anti-rust chemical on repaired and replaced panel.

		100.00
Labour Total	1120	2,720.00
Parts & Labour Total		7,139.76

*** This is a computer-generated document which requires no signature.***

page 3

Admin LG
 L/S 27/08/24.
 04 Days.

total: 3486.96

L/S: 27K ✓

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: