

ASSIGNMENT

From _____ Date: _____
 Estin _____
 OD / TP RES / CD RES / EVA / INV / MV
 To in _____ Vehicle No: _____
 at W/O _____
 of _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGF8322D Yr Regn: 2016 April
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Verel C.O. 1496
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 165180 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RU11109733
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/60R16
 R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 27/08/24

Survey held at N/S
 Des. of Damages: Frt / Rear O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

TP III

COE Expiry _____

Estimate given during : Yes (✓)
 1st Survey : No ()

MV :

PV :

Nett :

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 + RS. \$1

Photos

Others

1) Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

Report Format: _____

Report Format: _____



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TAN SOON HENG @ABDULLAH HALIM
BLK 448 YISHUN RING ROAD #07-74
SINGAPORE 760448

Contact : 88332686

TAX INVOICE

Repair Code : CLM18357

Date in : 30/07/2024

Vehicle Num. : SGF8322D

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11109733/L15B4029736

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>Derked</i>	1	910.20	✓ 910.20
FRONT RH DOOR BLACK TAPE <i>new</i>	1	26.40	✓ 26.40
FRONT RH DOOR GLASS OUTER MOULDING <i>new</i>	1	28.60	✓ 28.60
FRONT RH DOOR MECHANISM LOCK <i>new</i>	1	221.70	✓ 221.70
REAR LH FENDER <i>new</i>	1	790.20	✓ 790.20
REAR LH FENDER ARCH GARNISH <i>lit</i>	1	195.00	✓ 195.00
REAR RH DOOR <i>Derked</i>	1	883.40	✓ 883.40
REAR RH DOOR BLACK TAPE <i>new</i>	1	29.80	✓ 29.80
REAR RH DOOR CHECKER <i>new</i>	1	50.40	✓ 50.40
REAR RH DOOR GLASS OUTER MOULDING <i>new</i>	1	30.40	✓ 30.40
REAR RH DOOR GLASS REGULATOR WITH MOTOR <i>new</i>	1	412.50	✓ 412.50
REAR RH DOOR HINGE (LOWER) <i>new</i>	1	49.20	✓ 49.20
REAR RH DOOR HINGE (TOP) <i>new</i>	1	49.20	✓ 49.20
REAR RH DOOR INNER TRIM BOARD <i>new</i>	1	499.80	✓ 499.80
REAR RH DOOR LOCK STRIKER <i>new</i>	1	39.80	✓ 39.80
REAR RH DOOR MECHANISM LOCK <i>new</i>	1	299.70	✓ 299.70
REAR RH DOOR OUTER HANDLE <i>new</i>	1	93.70	✓ 93.70
REAR RH DOOR WEATHER STRIP <i>new</i>	1	149.20	✓ 149.20

*** This is a computer-generated document which requires no signature.***
page 1

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TAN SOON HENG @ABDULLAH HALIM
BLK 448 YISHUN RING ROAD #07-74
SINGAPORE 760448

Contact : 88332686

TAX INVOICE

Repair Code : CLM18357

Date in : 30/07/2024

Vehicle Num. : SGF8322D

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11109733/L15B4029736

REAR RH DOOR WEATHER STRIP (LOWER)	1	29.20	29.20
REAR RH DOOR WEATHER STRIP (VERTICAL)	1	39.40	39.40
ROCKER GARNISH RH	1	471.90	471.90
Subtotal before discount			5,299.70
Percentage discount 20%			1,059.94
Sub-total 1			4,239.76
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	50.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	50.00
REAR RH FENDER ARCH GARNISH CLIPS - SET	1	30.00	30.00
ROCKER GARNISH RH CLIPS - SET	1	50.00	50.00
Subtotal before discount			180.00
Percentage discount 0%			0.00
Sub-total 2			180.00
Parts-total			4,419.76

LABOUR

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

80.00
120.00
600.00
400.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TAN SOON HENG @ABDULLAH HALIM
 BLK 448 YISHUN RING ROAD #07-74
 SINGAPORE 760448

Contact : 88332686

TAX INVOICE

Repair Code : CLM18357

Date in : 30/07/2024

Vehicle Num. : SGF8322D

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11109733/L15B4029736

To apply anti-rust chemical on repaired and replaced panel.

	100.00
Labour Total	2,720.00
Parts & Labour Total	7,139.76

*** This is a computer-generated document which requires no signature.***

page 3

Admin G
 2/2 27/08/24.
 04 Days -

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: