



Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

TAN SOON HENG @ABDULLAH HALIM  
BLK 448 YISHUN RING ROAD #07-74  
SINGAPORE 760448

Contact : 88332686

## TAX INVOICE

Repair Code : CLM18357

Date in : 30/07/2024

Vehicle Num. : SGF8322D

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11109733/L15B4029736

### Parts and Labour Assesment

| Description of part                               | Qty | Unit Price | Amount   |
|---------------------------------------------------|-----|------------|----------|
| FRONT RH DOOR <i>Deided</i>                       | 1   | 910.20     | ✓ 910.20 |
| FRONT RH DOOR BLACK TAPE <i>nu</i>                | 1   | 26.40      | ✓ 26.40  |
| FRONT RH DOOR GLASS OUTER MOULDING <i>3x n</i>    | 1   | 28.60      | ✓ 28.60  |
| FRONT RH DOOR MECHANISM LOCK                      | 1   | 221.70     | ✓ 221.70 |
| REAR LH FENDER <i>Peris</i>                       | 1   | 790.20     | ✓ 790.20 |
| REAR LH FENDER ARCH GARNISH <i>lit</i>            | 1   | 195.00     | ✓ 195.00 |
| REAR RH DOOR <i>Deided</i>                        | 1   | 883.40     | ✓ 883.40 |
| REAR RH DOOR BLACK TAPE <i>nu</i>                 | 1   | 29.80      | ✓ 29.80  |
| REAR RH DOOR CHECKER <i>nu</i>                    | 1   | 50.40      | ✓ 50.40  |
| REAR RH DOOR GLASS OUTER MOULDING <i>nu</i>       | 1   | 30.40      | ✓ 30.40  |
| REAR RH DOOR GLASS REGULATOR WITH MOTOR <i>nu</i> | 1   | 412.50     | ✓ 412.50 |
| REAR RH DOOR HINGE (LOWER) <i>3x n</i>            | 1   | 49.20      | ✓ 49.20  |
| REAR RH DOOR HINGE (TOP) <i>3x n</i>              | 1   | 49.20      | ✓ 49.20  |
| REAR RH DOOR INNER TRIM BOARD <i>Cracked</i>      | 1   | 499.80     | ✓ 499.80 |
| REAR RH DOOR LOCK STRIKER <i>nu</i>               | 1   | 39.80      | ✓ 39.80  |
| REAR RH DOOR MECHANISM LOCK <i>nu</i>             | 1   | 299.70     | ✓ 299.70 |
| REAR RH DOOR OUTER HANDLE <i>3x n</i>             | 1   | 93.70      | ✓ 93.70  |
| REAR RH DOOR WEATHER STRIP <i>3x n</i>            | 1   | 149.20     | ✓ 149.20 |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*  
page 1

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

TAN SOON HENG @ABDULLAH HALIM  
BLK 448 YISHUN RING ROAD #07-74  
SINGAPORE 760448

Contact : 88332686

## TAX INVOICE

Repair Code : CLM18357

Date in : 30/07/2024

Vehicle Num. : SGF8322D

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11109733/L15B4029736

|                                            |   |        |          |
|--------------------------------------------|---|--------|----------|
| REAR RH DOOR WEATHER STRIP (LOWER)         | 1 | 29.20  | 29.20    |
| REAR RH DOOR WEATHER STRIP (VERTICAL)      | 1 | 39.40  | 39.40    |
| ROCKER GARNISH RH                          | 1 | 471.90 | 471.90   |
| Subtotal before discount                   |   |        | 5,299.70 |
| Percentage discount 20%                    |   |        | 1,059.94 |
| Sub-total 1                                |   |        | 4,239.76 |
| FRONT RH DOOR INNER TRIM BOARD CLIPS - SET | 1 | 50.00  | 50.00    |
| REAR RH DOOR INNER TRIM BOARD CLIPS - SET  | 1 | 50.00  | 50.00    |
| REAR RH FENDER ARCH GARNISH CLIPS - SET    | 1 | 30.00  | 30.00    |
| ROCKER GARNISH RH CLIPS - SET              | 1 | 50.00  | 50.00    |
| Subtotal before discount                   |   |        | 180.00   |
| Percentage discount 0%                     |   |        | 0.00     |
| Sub-total 2                                |   |        | 180.00   |
| Parts-total                                |   |        | 4,419.76 |

## LABOUR

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)  
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.  
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.  
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

80.00  
120 140.00  
600 1,200.00  
400 1,200.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

TAN SOON HENG @ABDULLAH HALIM  
 BLK 448 YISHUN RING ROAD #07-74  
 SINGAPORE 760448

Contact : 88332686

## TAX INVOICE

Repair Code : CLM18357

Date in : 30/07/2024

Vehicle Num. : SGF8322D

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11109733/L15B4029736

To apply anti-rust chemical on repaired and replaced panel.

x 100.00

**Labour Total**

**2,720.00**

**Parts & Labour Total**

**7,139.76**

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 3

Admin L  
 L/S 27/08/24.  
 04 Days -

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: