

**TTS EUROCARS PTE LTD**

2 DEFU SOUTH STREET 1, #04-04 DEFU INDUSTRIAL CITY

Date : 26/8/2024

**RE: VEHICLE REPAIR QUOTATION**

Vehicle Reg No  
 Name of Insured  
 Policy Number  
 Date of Accident  
 Tyre of Claim  
 Model  
 Chassis No

ms + Arnold  
 27/8/24  
 2/5 @ 2500  
 4 days  
 telephone Mr. Up

SCU1000Y

TAY LEE LING

P10431239R03

23/8/2024

THIRD PARTY CLAIM

TOYOTA WISH

JTDGG20W50J004937

LKK Auto Consultants hereby notify

the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts in a conspicuous manner
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be authorised and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

We are please to submit our estimate of repairs to the above mention vehicle.

**PARTS COST**

		QTY	UNIT/PC	Parts
1	REAR TAILGATE R	1	\$2,316.20	\$2,316.20 X
2	REAR TAILGATE EMBLEM SUC	1	\$80.20	\$80.20 X
3	REAR TAILGATE HINGE RH ^ ^	1	\$104.10	\$104.10 X
4	REAR TAILGATE HINGE LH ^ ^	1	\$104.10	\$104.10 X
5	REAR TAILGATR INNER PULL GARNISH ^ ^	1	\$95.20	\$95.20 X
6	REAR TAILGATE INNER TRIM GARNISH ^ ^	1	\$593.60	\$593.60 X
7	REAR TAILGATE MECHANISM LOCK SUC	1	\$660.00	\$660.00 X
8	RR TAILGATE MECHANISM LOCK STRIK ^ ^	1	\$67.80	\$67.80 X
9	RR TAILGATE ANTENNA SENSOR one 39160	1	\$486.60	\$486.60 ✓
10	RR TAILGATE OUTER GARNISH ^ ^	1	\$494.30	\$494.30 X
11	RR TAILGATE RUBBER GUIDE STOPPER ^ ^	2	\$37.30	\$74.60 X
12	RR TAILGATE WEATHERSTRIP ^ ^	1	\$456.60	\$456.60 X
13	END PANEL 20/24 902.80	1	\$951.70	\$951.70 ✓
14	REAR BUMPER 20/24 831.50	1	\$994.50	\$994.50 ✓
15	REAR BUMPER CLIPS neu	12	\$5.70	\$68.40 ✓
16	REAR BUMPER SIDE RETAINERS ^ ^	2	\$246.10	\$492.20 X
17	REAR BUMPER REINFORCEMENT NS	1	\$650.50	\$650.50 X
18	REAR BUMPER REFLECTORS ^ ^	2	\$81.70	\$163.40 X
19	REAR BUMPER REVERSE SENSOR SUC	2	\$550.00	\$1,100.00 X
				\$9,954.00
	LESS 25%			-\$2,488.50
				\$7,465.50

**LABOUR**

1	TO DISMANTLE & REFIX REAR SENSOR	\$300.00 30
2	TO CHECK TAILLAMP WIRING SYSTEM & FUNCTION ETC.	\$250.00 20
3	TO APPY TUFF COATING FOR AFFECT	\$300.00 30
4	TO PANEL BEATING, DISMANTLE & REFIX REAR TAILGATE, END PANEL REAR BUMPER AND ALL NECESSARY ETC.	\$2,500.00 800
5	TO SPRAY PAINTING ON REAR TAILGATE REAR BUMPER AND ALL NECESSARY ETC.	\$2,200.00 600

\$13,015.50

2-2194.30  
 252  
 1648.72

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.