

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI24080455/ENP3E2**Date:** 30/08/2024REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MZD04636
<b>Claimant Vehicle No :</b>	SH6224P	<b>Insured Vehicle No :</b>	SLV635K
Date of Loss:	26/08/2024	Nature of Claim:	TP
		Claim No:	M2404875

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SH6224P</b>	Engine No:	2ZRS066073
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU403564974
Reg. Date:	03/10/2017 (Man. Year: 2017)	Odometer:	909777 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,307.02	1,354.96	2,952.06	68.54
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,520.00	1,160.00	360.00	23.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,839.02</b>	<b>2,526.96</b>	<b>3,312.06</b>	<b>56.72</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>(S\$)</b>	5,839.02	2,000.00	3,839.02	65.75
<b>+ GST 9.00/9.00% (S\$)</b>	525.51	180.00	345.51	65.75
<b>Nett Amount (S\$)</b>	<b>6,364.53</b>	<b>2,180.00</b>	<b>4,184.53</b>	<b>65.75</b>

INSPECTION

Date of Assignment:	27/08/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	27/08/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2024)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH6224P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER SUB ASSY LH	Dented	1,111.93 FL	*1,111.93 FL
2	1		*FRONT FENDER HYBRID EMBLEM LH	Necessary	86.50 FL	*86.50 FL
3	1		*FRONT FENDER SHIELD LH	Not Necessary	198.50 FL	*- FL
4	1		*FRONT BUMPER COVER	Broken	586.18 FL	*586.18 FL
5	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	82.30 FL	*- FL
6	1		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*HEADLAMP LH	Not Necessary	2,735.28 FL	*- FL
8	1		*DAYLIGHT LH	Not Necessary	920.00 FL	*- FL
					<b>Sub Total (\$\$)</b>	<b>5,742.69 1,806.61</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,435.67 451.65</b>
					<b>Total Parts (\$\$)</b>	<b>4,307.02 1,354.96</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (S\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	570.00
2	SPRAY PAINTING CHARGE	New	600.00	560.00
3	CHECK LIGHTING/ WIRING	New	60.00	30.00
4	TUFF KOTE	New	60.00	0.00
Gross Labour Cost (S\$)			1,520.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >