

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI24060129/EVH3E2
Date: 07/08/2024**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG23012641
Claimant Vehicle No :	SLV4939H	Insured Vehicle No :	GBH7299T
Date of Loss:	15/06/2024	Nature of Claim:	TP
		Claim No:	CDMCG24001485

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV4939H	Engine No:	2ZR8117900
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Chassis No:	ZYX102043470
Reg. Date:	29/12/2017 (Man. Year: 2017)	Odometer:	75979 km
Colour:	Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,058.36	3,829.33	229.03	5.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	830.00	850.00	50.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,738.36	4,659.33	1,079.03	18.80
+ GST 9.00/9.00% (S\$)	516.45	419.34	97.11	18.80
Nett Amount (S\$)	6,254.81	5,078.67	1,176.14	18.80

INSPECTION

Date of Assignment:	18/06/2024	
Date Inspected:	19/06/2024	Inspected At: Toh Ah Swee Spray Painting Co (HQ) No 60, Jalan Lam Huat, #07-33/34 Carros Centre Singapore 737869
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Aug 2024)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV4939H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR	Dented	1,683.88 FL	*1,683.88 FL
2	1		*RH FRONT DOOR GARISH	Cut	432.25 FL	*432.25 FL
3	1		*RH FRONT FENDER	Dented	1,056.25 FL	*1,056.25 FL
4	1		*RH FRONT FENDER EMBLEM	Necessary	140.38 FL	*140.38 FL
5	1		*RH FRONT FENDER GARISH	Cut	184.38 FL	*184.38 FL
6	1		*RH FRONT FENDER INNER SHIELD	Not Necessary	305.38 FL	*- FL
7	1		*RH SIDE MIRROR	Broken	1,608.63 FL	*1,608.63 FL
					Sub Total (S\$)	5,411.15
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,352.79
					Total Parts (S\$)	4,058.36

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SPRAY PAINTING ON AFFECTED BODY PART	New	700.00	400.00
2	TO PANEL BEATING, REPLACE BODY PART AND WEILDING AND FITTING AND ALIGNMENT	New	800.00	400.00
3	TO CHECK SIDE MIRROR AND DOOR MECHANISM WIRING	New	180.00	30.00
Gross Labour Cost (\$\$)			1,680.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >