

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0639/2024/KS
DATE : 28-Aug-24
WIP : 28740

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Rasul,

11 Days + 1 Sun - OK - Allan Boo

23-Oct-24

OWNER'S NAME : MR TAN AIK PING
ADDRESS : 146 QUEEN'S AVENUE
SINGAPORE 758600
TELEPHONE : HP +65 93630405
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220129564
VEHICLE NO : **SDD 6608 P**
MODEL CODE : A6 DESIGN 2.0 TFSI S TRONIC
MODEL YEAR : 11/11/2022
ENGINE NO : DKY 016762
CHASSIS NO : WAUZZZF23NN031079
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Aug-24
PLACE OF ACCIDENT : SENTOSA GATEWAY TOWARDS TELOK BLANGAH RD
BEFORE UNDERPASS

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDD 6608 P.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	\$ 800.00
3	TO REMOVE AND REINSTALL RHS WING MIRROR TO FACILTATE DOOR PAINTING.	S/N \$	280.00	\$ 280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,500.00	\$ 1,750.00
5	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, BONNET AND RHS FRONT DOOR.	\$	6,400.00	\$ 2,750.00
6	TO CARRY OUT 360 DEGREE CAMERA CALIBRATION WITH VAS TOOLS.	S/N \$	800.00	\$ 800.00
7	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	292.00	\$ 292.00
	ADD LABOUR - SUPPLEMENTARY			\$ 4,500.00
TOTAL LABOUR CHARGES		:	\$ 15,552.00	\$ 11,652.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDD 6608 P.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 3,380.00	\$	2,704.00
2	FRONT BUMPER FIXING PARTS	1	\$ 696.00		
3	FRONT BUMPER PLATE	1	\$ 54.00		
4	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 279.00	\$	223.20
5	FRONT BUMPER ADAPTOR - LH / RH	2	\$ 100.00	\$	79.36
6	FRONT BUMPER REINFORCEMENT BRACKET - RH	1	\$ 140.00	\$	111.60
7	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 192.00	\$	153.60
8	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 263.00	\$	210.40
9	FRONT BUMPER SPOILER	1	\$ 316.00		
10	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 544.00	\$	434.80
11	FRONT BUMPER AIR GUIDE - RH INNER	1	\$ 42.00	\$	32.88
12	FRONT BUMPER AIR GUIDE - RH OUTER	1	\$ 33.00	\$	25.68
13	RADIATOR GRILLE	1	\$ 2,725.00	\$	2,180.00
14	RADIATOR GRILLE COVER	1	\$ 72.00		
15	"360" DEGREE CAMERA COVER	1	\$ 65.00		
16	"360" DEGREE CAMERA BRACKET	1	\$ 116.00		
17	FRONT PARKING AID SENSOR	2	\$ 629.00	\$	251.60
18	FRONT SIDE ASSIST PARKING AID SENSOR	1	\$ 315.00		
19	FRONT PARKING AID SENSOR SEAL RING	6	\$ 17.00		
20	FRONT BUMPER GUIDE SECTION - RH	1	\$ 56.00	\$	44.48
SUB TOTAL SPARE PARTS		:	\$ 10,034.00	\$	6,451.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDD 6608 P.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 6,451.60
21	FRONT BUMPER TOP COVER	1 \$	158.00	\$ 126.00
22	"OIL STANDARD" STICKER	1 \$	25.00	\$ 19.44
23	"CAUTION" STICKER	1 \$	25.00	\$ 19.44
24	FRONT FOAM FILLER PIECE	1 \$	283.00	\$ 226.40
25	FRONT REINFORCEMENT BEAM	1 \$	1,232.00	\$ 985.60
26	OUTSIDE TEMP SENSOR BRACKET	1 \$	28.00	\$ 22.40
27	FRONT REINFORCEMENT BEAM SUPPORT - LH / RH	2 \$	77.00	\$ 60.48
28	FRONT BUMPER BRACKET - RH	1 \$	68.00	\$ 54.40
29	HEADLIGHT MOUNTING - LH / RH	2 \$	294.00	\$ 117.60
30	LED HEADLIGHT - RH	1 \$	10,397.00	\$ 8,317.60
31	LED HEADLIGHT SPACER - RH	2 \$	100.00	\$ 39.84
32	LIFT CYLINDER - RH	1 \$	238.00	
33	LIFT CYLINDER HOSE - RH	1 \$	233.00	
34	LIFT CYLINDER BRACKET - RH	1 \$	8.00	
35	LOCK CARRIER TOP COVER - RH	1 \$	55.00	\$ 43.44
36	FRONT FENDER - LH / RH	2 \$	3,708.00	\$ 1,483.20
37	FRONT FENDER ATTACHMENT PARTS - RH	1 \$	94.00	
38	FRONT FENDER BRACE - RH FRONT	1 \$	194.00	\$ 154.40
39	FRONT FENDER BRACKET - RH UPPER	1 \$	55.00	\$ 43.44
40	FRONT WHEEL HOUSING LINER - RH	1 \$	332.00	\$ 265.60
SUB TOTAL SPARE PARTS			\$ 17,604.00	\$ 18,430.88

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDD 6608 P.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 18,430.88
41	FRONT WHEEL SPOILER - RH	1 \$	207.00	\$ 165.60
42	FRONT WHEEL SPOILER TRIM - RH	1 \$	45.00	
43	BONNET	1 \$	6,276.00	\$ 5,020.80
44	BONNET ATTACHMENT PARTS	1 \$	262.00	
45	BONNET HINGE - LH / RH	2 \$	410.00	\$ 335.20
46	BONNET SHOCK ABSORBER	1 \$	143.00	
47	BONNET SOUND ABSORBER	1 \$	398.00	
48	BONNET IMPACT PROTECTION - LH / RH	2 \$	46.00	\$ 38.56
49	BONNET IMPACT PROTECTION - CENTER	1 \$	56.00	\$ 44.08
50	BONNET STRIKER - LH / RH	2 \$	274.00	\$ 219.20
51	FRONT FENDER TOP COVER - RH	1 \$	41.00	\$ 32.40
52	FRONT FENDER TOP SEALING STRIP - RH	1 \$	37.00	
53	BONNET LOCK - LH RH	2 \$	399.00	
54	BONNET BOWDEN CABLE - CENTER	1 \$	71.00	
55	BONNET RELEASE ELEMENT	1 \$	73.00	
56	BONNET BOWDEN CABLE - COVER	1 \$	12.00	
57	RADIATOR AIR GUIDE - LH / RH	2 \$	108.00	\$ 42.24
58	RADIATOR AIR GUIDE - UPPER / LOWER	2 \$	84.00	
59	HORN - RH	1 \$	162.00	
60	HORN BRACKET - RH	1 \$	59.00	
61	INTERCOOLER PRESSURE HOSE - RH	1 \$	375.00	
62	WINDSCREEN WATER DEFLECTOR STRIP - RH	1 \$	74.00	\$ 58.80
63	FRONT NO PLATE	S/N \$	60.00	\$ 60.00
	ADD PARTS - SUPPLEMENTARY			\$ 2,097.52
64	SUNDRIES	\$	800.00	\$ 54.80
TOTAL SPARE PARTS			\$ 38,110.00	\$ 26,600.08
TOTAL LABOUR CHARGES			\$ 15,552.00	\$ 11,652.00
GRAND TOTAL			\$ 53,662.00	\$ 38,252.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0639/2024/KS 3-Sep-24 GLORY 1 of 1 SDD 6608 P A6 DESIGN 2.0 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,800.00	\$ 1,800.00
2	TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	\$ 1,200.00
3	TO REMOVE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 1,500.00	\$ 1,500.00
		LABOUR TOTAL	\$ 4,500.00
<u>Parts</u>			
1	FRONT LOCK CARRIER	\$ 1,542.00	\$ 1,233.60
2	FRONT BUMPER TOP COVER FOAME FILLER PIECE RHS	\$ 48.00	\$ 37.92
3	RHS FRONT DOOR WINDOW SLOT SEAL	\$ 249.00	\$ 198.80
4	RHS FRONT FENDER TOP LEDGE COVER	\$ 45.00	\$ 35.36
5	AIR FILTER BOX	\$ 371.00	\$ 296.40
6	READY MIX COOLANT 1.0L	6 \$ 332.00	\$ 265.44
7	STICKER FOR AIR CONDITIONER	\$ 38.00	\$ 30.00
		PARTS TOTAL	\$ 2,097.52
	GRAND TOTAL	\$ 7,125.00	\$ 6,597.52

For Premium Automobiles Pte Ltd

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT