


PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDD 6608 P.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 /	
3	TO REMOVE AND REINSTALL RHS WING MIRROR TO FACILTATE DOOR PAINTING.	S/N \$ 280.00 /	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,500.00 1750 /	
5	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, BONNET AND RHS FRONT DOOR.	\$ 6,400.00 2750 /	
6	TO CARRY OUT 360 DEGREE CAMERA CALIBRATION WITH VAS TOOLS.	S/N \$ 800.00 /	
7	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 292.00 /	
TOTAL LABOUR CHARGES		: \$ 15,552.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDD 6608 P.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>tom</i>	1	\$ 3,380.00	2704
2	FRONT BUMPER FIXING PARTS <i>Xm</i>	1	\$ 696.00	
3	FRONT BUMPER PLATE <i>HA ? xsuc</i>	1	\$ 54.00	
4	FRONT BUMPER CLOSING ELEMENT - CENTER <i>cm</i>	1	\$ 279.00	223.20
5	FRONT BUMPER ADAPTOR - LH / RH <i>?cm</i>	2	\$ 100.00	75.36
6	FRONT BUMPER REINFORCEMENT BRACKET - RH <i>?bt</i>	1	\$ 140.00	111.60
7	FRONT BUMPER GRILLE - LOWER CENTRE <i>cm</i>	1	\$ 192.00	153.60
8	FRONT BUMPER CLOSING ELEMENT - LOWER <i>cm</i>	1	\$ 263.00	210.40
9	FRONT BUMPER SPOILER <i>?xsuc</i>	1	\$ 316.00	
10	FRONT BUMPER AIR GUIDE GRILLE - RH <i>mis</i>	1	\$ 544.00	434.80
11	FRONT BUMPER AIR GUIDE - RH INNER <i>?cm</i>	1	\$ 42.00	32.88
12	FRONT BUMPER AIR GUIDE - RH OUTER <i>?cm</i>	1	\$ 33.00	25.68
13	RADIATOR GRILLE <i>cm</i>	1	\$ 2,725.00	2180
14	RADIATOR GRILLE COVER <i>?xsuc</i>	1	\$ 72.00	
15	"360" DEGREE CAMERA COVER <i>Xm</i>	1	\$ 65.00	
16	"360" DEGREE CAMERA BRACKET <i>Xm</i>	1	\$ 116.00	
17	FRONT PARKING AID SENSOR <i>mis</i>	1	\$ 629.00	251.60
18	FRONT SIDE ASSIST PARKING AID SENSOR <i>?xsuc</i>	1	\$ 315.00	
19	FRONT PARKING AID SENSOR SEAL RING <i>Xm</i>	6	\$ 17.00	
20	FRONT BUMPER GUIDE SECTION - RH <i>?cm</i>	1	\$ 56.00	44.48
SUB TOTAL SPARE PARTS		:	\$ 10,034.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183


EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDD 6608 P.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT BUMPER TOP COVER <i>cm</i>	1	\$ 158.00	126	
22	"OIL STANDARD" STICKER <i>m</i>	1	\$ 25.00	19.44	
23	"CAUTION" STICKER <i>m</i>	1	\$ 25.00	19.44	
24	FRONT FOAM FILLER PIECE <i>cm</i>	1	\$ 283.00	226.40	
25	FRONT REINFORCEMENT BEAM <i>?bt</i>	1	\$ 1,232.00	985.60	
26	OUTSIDE TEMP SENSOR BRACKET <i>?cm</i>	1	\$ 28.00	22.40	
27	FRONT REINFORCEMENT BEAM SUPPORT - LH / RH <i>?4</i>	2	\$ 77.00	60.48	
28	FRONT BUMPER BRACKET - RH <i>?cm</i>	1	\$ 68.00	54.40	
29	HEADLIGHT MOUNTING - LH / RH <i>cm</i>	1	\$ 294.00	117.60	
30	LED HEADLIGHT - RH <i>cm</i>	1	\$ 10,397.00	8317.60	
31	LED HEADLIGHT SPACER - RH <i>?cm</i>	1	\$ 100.00	39.84	
32	LIFT CYLINDER - RH <i>?xsvl</i>	1	\$ 238.00		
33	LIFT CYLINDER HOSE - RH <i>?xsvl</i>	1	\$ 233.00		
34	LIFT CYLINDER BRACKET - RH <i>?xsvl</i>	1	\$ 8.00		
35	LOCK CARRIER TOP COVER - RH <i>?cm</i>	1	\$ 55.00	43.44	
36	FRONT FENDER - LH / RH <i>R</i>	1	\$ 3,708.00	1483.20	
37	FRONT FENDER ATTACHMENT PARTS - RH <i>m</i>	1	\$ 94.00		
38	FRONT FENDER BRACE - RH FRONT <i>?4</i>	1	\$ 194.00	154.40	
39	FRONT FENDER BRACKET - RH UPPER <i>m</i>	1	\$ 55.00	43.44	
40	FRONT WHEEL HOUSING LINER - RH <i>cm</i>	1	\$ 332.00	265.60	
SUB TOTAL SPARE PARTS			\$ 17,604.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183


EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDD 6608 P.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT WHEEL SPOILER - RH <i>? de /</i>	1	\$ 207.00	165.60
42	FRONT WHEEL SPOILER TRIM - RH <i>? xsu</i>	1	\$ 45.00	
43	BONNET <i>bf /</i>	1	\$ 6,276.00	5020.80
44	BONNET ATTACHMENT PARTS <i>xm</i>	1	\$ 262.00	
45	BONNET HINGE - LH / RH <i>bf /</i>	2	\$ 410. 210.00	335.20
46	BONNET SHOCK ABSORBER <i>xm</i>	1	\$ 143.00	
47	BONNET SOUND ABSORBER <i>xm</i>	1	\$ 398.00	
48	BONNET IMPACT PROTECTION - LH / RH <i>m -</i>	2	\$ 46.00	38.56
49	BONNET IMPACT PROTECTION - CENTER <i>m -</i>	1	\$ 56.00	44.08
50	BONNET STRIKER - LH / RH <i>? bf /</i>	2	\$ 274.00	219.20
51	FRONT FENDER TOP COVER - RH <i>de -</i>	1	\$ 41.00	32.40
52	FRONT FENDER TOP SEALING STRIP - RH <i>? xsu</i>	1	\$ 37.00	
53	BONNET LOCK - LH RH <i>? xsu</i>	2	\$ 399.00	
54	BONNET BOWDEN CABLE - CENTER <i>? xsu</i>	1	\$ 71.00	
55	BONNET RELEASE ELEMENT <i>? xsu</i>	1	\$ 73.00	
56	BONNET BOWDEN CABLE - COVER <i>? xsu</i>	1	\$ 12.00	
57	RADIATOR AIR GUIDE - LH / RH <i>? cm</i>	2	\$ 108.00	42.24
58	RADIATOR AIR GUIDE - UPPER / LOWER <i>? xsu</i>	2	\$ 84.00	
59	HORN - RH <i>? xm</i>	1	\$ 162.00	
60	HORN BRACKET - RH <i>? xsu</i>	1	\$ 59.00	
61	INTERCOOLER PRESSURE HOSE - RH <i>? xsu</i>	1	\$ 375.00	
62	WINDSCREEN WATER DEFLECTOR STRIP - RH <i>cut /</i>	1	\$ 74.00	58.80
63	FRONT NO PLATE <i>bf /</i>	S/N	\$ 60.00	/
64	SUNDRIES <i>? xm</i>		\$ 800.00	54.80
TOTAL SPARE PARTS			: \$	20,306.00
TOTAL LABOUR CHARGES			: \$	15,552.00
GRAND TOTAL			: \$	35,858.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasul - 4p 9001w68
: 28/08/24
: 8 days + 3 = 11 days
: EXCESS TBA
: Repair
: Res 54 paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before ~~after~~ spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0639/2024/KS
3-Sep-24
GLORY
1 of 1
SDD 6608 P
A6 DESIGN 2.0 TFSI S TRONIC

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,800.00	/
2	TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	/
3	TO REMOVE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 1,500.00	/
Parts			
1	FRONT LOCK CARRIER <i>cr</i>	\$ 1,542.00	1233.6
2	FRONT BUMPER TOP COVER FOAME FILLER PIECE RHS <i>cr</i>	\$ 48.00	37.92
3	RHS FRONT DOOR WINDOW SLOT SEAL <i>at</i>	\$ 249.00	198.8
4	RHS FRONT FENDER TOP LEDGE COVER <i>at</i>	\$ 45.00	35.36
5	AIR FILTER BOX <i>cr</i>	\$ 371.00	296.4
6	READY MIX COOLANT 1.0L <i>new</i>	6 \$ 332.00	265.44
7	STICKER FOR AIR CONDITIONER <i>new</i>	\$ 38.00	30
GRAND TOTAL		\$ 7,125.00	

For Premium Automobiles Pte Ltd

3 days add on

Authorised Signature