



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. : SAC2401825

INV Date : 12-12-2024

Reference CD/CTI24080458/Kma3q2

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SNM 3435A
Insured Veh. SNP 9346T
Claim No. SNM24D204815
Policy No. DMPCSNW00038312400
Accident Date 23/08/2024
Inspection Date 27/08/2024

Description	Amount
Third Party Express Settlement	400.00
Sub-Total	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909		Ref: Date: Code:	CD/CT124080458/Kma3q2 12/12/2024 CTI
1. Policy Particulars :- DIRECT SETTLEMENT			
Insured Veh.	SNP 9346T	Veh. Inspected	SNM 3435A
Policy No.	DMPCSNW00038312400	Coverage	0
Claim No.	SNM24D204815	Excess	\$0.00
Assign From	LYNN KHONG	Assign Date	27/08/2024
2. Vehicle Details			
Make & Model	TOYOTA PRIUS C 1.5 HYBRID CVT	C.C	1497
Engine No.	1NZR521759	Year of Reg.	28/06/2017
Chassis No.	JTDKD3B3701597227	Colour	METALLIC BLACK
Odometer	323050 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
R/H Front Tyre	185/65R15	WESTLAKE	4
L/H Front Tyre	185/65R15	WESTLAKE	4
R/H Rear Tyre	185/65R15	YOKOHAMA	7
L/H Rear Tyre	185/65R15	YOKOHAMA	7
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/08/2024	Inspection Date	27/08/2024
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNM 3435A

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TAILGATE	TO REPAIR SEE LABOUR	\$900.00	\$0.00
1	REAR TAILGATE TOYOTA EMBLEM	NOT NECESSARY	\$80.00	\$0.00
1	REAR TAILGATE PRIUS C EMBLEM	NOT NECESSARY	\$75.00	\$0.00
1	REAR TAILGATE HYBRID EMBLEM	NOT NECESSARY	\$80.00	\$0.00
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	\$285.80	\$0.00
1	REAR TAIL LAMP RH	MTG CRACKED	\$530.20	\$530.20
1	REAR TAIL LAMP BRACKET RH	CRACKED	\$75.60	\$75.60
1	REAR BUMPER	BENT	\$848.70	\$848.70
1	REAR BUMPER REINFORCEMENT	BENT	\$590.60	\$590.60
1	REAR BUMPER SIDE BRACKET RH	DISTORTED	\$85.40	\$85.40
1	REAR END PANEL	BENT	\$556.80	\$556.80
1	REAR END PANEL UPPER COVER	SERVICEABLE	\$115.20	\$0.00
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
	LESS 25.00% DISCOUNT		(\$1,055.83)	(\$671.83)
			\$3,167.47	\$2,015.47

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$50.00
1	REAR BUMPER REVERSE SENSOR (SN)	DENTED	\$300.00	\$200.00
1	REAR END PANEL JOINT SEALANT (SN)	NOT NECESSARY	\$100.00	\$0.00
1	REAR END PANEL UPPER COVER CLIPS (SN)	NOT NECESSARY	\$40.00	\$0.00
			\$570.00	\$250.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF REAR TAILGATE AND REAR FENDER RH.		\$1,000.00	\$450.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, REAR FENDER RH & ETC		\$1,000.00	\$600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM & ETC .BACK TO ORIGINAL OPERATIONS	NOT NECESSARY	\$120.00	\$0.00
	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN SEALANT & ETCS	NOT NECESSARY	\$150.00	\$0.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC		\$120.00	\$50.00
	TO DIAGNOSIS FAULT CODE & ETC	NOT NECESSARY	\$200.00	\$0.00
	TO CHECK WIRING & ELECTRICAL SYSTEM		\$120.00	\$15.00
			\$2,710.00	\$1,115.00
GRAND TOTAL			\$6,447.47	\$3,380.47
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				\$2,700.00
Report Ref No: CD/CTI24080458/Kma3q2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNM 3435A



PHOTOGRAPHS FOR VEHICLE NO. : SNM 3435A



PHOTOGRAPHS FOR VEHICLE NO. : SNM 3435A





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. : SNM 3435A





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SNM 3435A



PHOTOGRAPHS FOR VEHICLE NO. : SNM 3435A





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SNM 3435A

