

Date: 26/08/2024
 Vehicle No: SNM3435A
 Model: TOYOTA PRIUS C 1.5 HYBRID
 Chassis: JTDKD3B3701597227-2017
 Reg.Year: 2017

Not Authored
L1 Rep &

Third Party Insurer: CHINA TAIPING
 Third Party Veh No: SNP9346T
 Date of Accident: 23/08/2024
 Estimator: TING AN
 Surveyor:

Recovery After Rain
3-4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		R \$900.00
2	REAR TAILGATE "TOYOTA" EMBLEM	1		na \$80.00
3	REAR TAILGATE "PRIUS C" EMBLEM	1		na \$75.00
4	REAR TAILGATE "HYBRID" EMBLEM	1		na \$80.00
5	REAR TAILGATE WEATHERSTRIP	1		R \$285.80
6	REAR TAIL LAMP RH	1		\$530.20
7	REAR TAIL LAMP BRACKET RH	1		\$75.60
8	REAR BUMPER	1		Ry \$848.70
9	REAR BUMPER REINFORCEMENT	1		\$590.60
10	REAR BUMPER SIDE BRACKET RH	1		Diy \$85.40
11	REAR END PANEL	1		R \$556.80
12	REAR END PANEL UPPER COVER	1		R \$115.20
13	REAR FENDER RH	1		REPAIR
SUB TOTAL				\$4,223.30
LESS 25%				-\$1,055.83
PARTS TOTAL				\$3,167.48

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		na \$80.00
2	REAR BUMPER CLIPS	1		mc \$50.00
3	REAR BUMPER REVERSE SENSOR	1		nd \$300.00
4	REAR END PANEL JOINT SEALANT	1		na \$100.00
5	REAR END PANEL UPPER COVER CLIPS	1		na \$40.00
S/N TOTAL				\$140.00

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-06 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 26/08/2024
 Vehicle No: SNM3435A
 Model: TOYOTA PRIUS C 1.5 HYBRID
 Chassis: JTDKD3B3701597227-2017
 Reg.Year: 2017

Third Party Insurer: CHINA TAIPING
 Third Party Veh No: SNP9346T
 Date of Accident: 23/08/2024
 Estimator: TING AN
 Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	\$1,000.00	250
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, REAR FENDER RH & ETC.	\$1,000.00	400
LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	na \$120.00	X
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETEC.	na \$150.00	X
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$120.00	301
TO DAIGNOSIS FAULT CODE & ETC.	na \$200.00	X
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$120.00	151
	LABOUR TOTAL	\$2,710.00

TING AN	TOTAL	\$6,017.48
---------	--------------	-------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date: