



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS ETHOZ PROTECT PTE LTD	Ref:	CS/TP24080460/Uqp3
30 BUKIT BATOK CRESCENT SINGAPORE SINGAPORE 658075	Date:	15/10/2024
	Code:	TP513

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	-	Veh. Inspected	PD 126K
Policy No.	-	Coverage	0
Claim No.	-	Excess	\$0.00
Assign From	-	Assign Date	27/08/2024

### 2. Vehicle Details

Make & Model	TOYOTA HIACE HIGH ROOF COMMUTER (A)	C.C	2982
Engine No.	1KDB108615	Year of Reg.	31/03/2022
Chassis No.	JTFST22P600040547	Colour	WHITE
Odometer	136538 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	YOKOHAMA	7
L/H Front Tyre	195R15	YOKOHAMA	7
R/H Rear Tyre	195R15	YOKOHAMA	7
L/H Rear Tyre	195R15	YOKOHAMA	7

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	18/08/2024	Inspection Date	27/08/2024
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days