

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547617
FAX :

Date : 27/08/2024

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 18/08/2024

Vehicle No : PD - 126-K

Make & Model : TOYOTA HIACE HIGH ROOF COMMUTER 3.0

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>1st</u> <u>Item</u>			
1	FRONT BUMPER <i>cut/de</i>	720.00	/
1	FRONT BUMPER RETAINER RH <i>11</i>	162.00	X
10	FRONT BUMPER CLIPS <i>new</i>	50.00	/
1	FRONT CORNER PANEL RH <i>n</i>	306.00	X
1	FRONT WINDSCREEN PILLAR RH <i>n</i>		
1	HEADLAMP RH <i>S n</i>	850.00	/
1	WING MIRROR ASSY RH <i>320</i>	680.00	/
1	FRONT DOOR RH <i>22 / self</i>	1,630.00	/
1	FRONT DOOR CHECKER RH <i>721</i>	153.00	/

RESTORE

Date : 27/08/2024

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 18/08/2024

Vehicle No : PD - 126-K

Make & Model : TOYOTA HIACE HIGH ROOF COMMUTER 3.0

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT DOOR WEATHERSTRIP RH <i>neu</i>	245.00	<i>/</i>
1	FRONT DOOR STEP GARNISH RH <i>TD-1</i>	187.00	<i>/</i>
1	FRONT WHEEL HUB CAP RH <i>CNE</i>	180.00	<i>/</i>
1	FRONT MUDFLAP RH <i>Dis</i>	165.00	<i>/</i>
1	B PILLAR RH <i>n</i>	RESTORE	<i>X</i>
1	REAR FENDER RH <i>n</i>	RESTORE	<i>X</i>
1	REAR BUMPER <i>n</i>	RESTORE	<i>X</i>
1	TAILAMP RH <i>11</i>	330.00	<i>X</i>

Date : 27/08/2024

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 18/08/2024

Vehicle No : PD - 126-K

Make & Model : TOYOTA HIACE HIGH ROOF COMMUTER 3.0

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	5658.00	
	Discount 25% On Parts	(1414.50)	
	<u>Special Nett Item</u>		
1	ADVERTISEMENT STICKER RH <i>111</i>	300.00	✓
	Sub Total	300.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	1,200.00	<i>1000</i>
	TO RESPRAY AFFECTED AREAS	1,200.00	✓
	TO REMOVE AND TRANSFER DOOR COMPONENTS	150.00	<i>60</i>
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	<i>20</i>

Date : 27/08/2024

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 18/08/2024

Vehicle No : PD - 126-K

Make & Model : TOYOTA HIACE HIGH ROOF COMMUTER 3.0

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	RUST PROOFING	100.00	50
	Sub Total	2680.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7,223.50

Remarks:

not Authored

SUB TOTAL

GST 9.0 %

650.12

TOTAL

7,873.61

Surveyor's name:

morans Hui

Principal's name: ETHOZ Group Ltd

Survey Date & Time:

27/8/24 @ 1.20 pm

2/5 \$5000
the phone app rep -
5 days

2 4860
252
3645
300
2330
6275
22
5020