

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TPECICS.

Hui Rong

TAX INVOICE

MAXLINES DISTRIBUTORS
92 COMMONWEALTH DRIVE #01-716
COMMONWEALTH 16
SINGAPORE 140092

Repair Code : CLM16406

Date in : 26/08/2024

Vehicle Num. : GBF4531C

Model : TOYOTA HIACE 3.0 M

Chassis/Eng# : KDH2010190610/1KD2592929

Contact : 96391418

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON BLOWER ASSY <i>Cracked</i>	1	1053.40	1,053.40 ✓
AIRCON COOLING COIL ASSY <i>new</i>	1	3837.80	3,837.80 +
FRONT BONNET <i>Dented</i>	1	1082.50	866 1,082.50 ✓
FRONT BONNET 'LOGO' EMBLEM <i>new</i>	1	59.60	59.60 ✓
FRONT BONNET HINGES L/R <i>new</i>	2	62.30	124.60 +
FRONT BONNET INNER RUBBER STOPPER L/R <i>new</i>	2	18.40	36.80 +
FRONT BONNET MECHANISM LOCK <i>new</i>	1	99.80	99.80 +
FRONT BUMPER <i>Distorted</i>	1	573.60	573.60 ✓
FRONT BUMPER FOGLAMP GARNISH L/R <i>new</i>	2	106.00	212.00 +
FRONT BUMPER INNER REINFORCEMENT VERTICAL BRACKET LH <i>new</i>	1	157.00	157.00 +
FRONT BUMPER LOWER GRILLE <i>new</i>	1	188.70	188.70 +
FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	379.40	379.40 ✓
FRONT BUMPER REINFORCEMENT BRACKET LH <i>new</i>	1	120.70	120.70 +
FRONT BUMPER SIDE RETAINER L/R <i>LH smashed</i>	2	151.80	303.60 151.80
FRONT BUMPER TOW HOOK COVER L/R <i>new</i>	2	30.10	60.20 +
FRONT DASH PANEL <i>Regis</i>	1	909.20	909.20 +
FRONT DASH PANEL INSULATOR <i>new</i>	1	281.00	281.00 +
FRONT DASHBOARD <i>new</i>	1	1028.50	1,028.50 +

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

MAXLINES DISTRIBUTORS
 92 COMMONWEALTH DRIVE #01-716
 COMMONWEALTH 16
 SINGAPORE 140092

Contact : 96391418

TAX INVOICE

Repair Code : CLM16406

Date in : 26/08/2024

Vehicle Num. : GBF4531C

Model : TOYOTA HIACE 3.0 M

Chassis/Eng# : KDH2010190610/1KD2592929

FRONT DASHBOARD REINFORCEMENT <i>not in</i>	1	805.40	805.40	+
FRONT FLOOR PANEL <i>Repair</i>	1	1270.60	1,270.60	+
FRONT FLOOR PANEL WIRE HARNESS <i>not in</i>	1	526.70	526.70	+
FRONT FLOOR PANEL WIRE HARNESS COVER <i>not in</i>	1	174.50	174.50	✓
FRONT FUSE BOX <i>not in</i>	1	651.70	651.70	+
FRONT GRILLE BASE	1	602.60	602.60	✓
FRONT GRILLE LOWER OUTER COVER	1	406.70	406.70	✓
FRONT GRILLE TOP OUTER COVER	1	235.00	235.00	✓
FRONT HEADLAMP L/R <i>not in</i>	2	3979.50	7959.00	✓
FRONT LH CORNER PANEL <i>not in</i>	1	284.60	284.60	✓
FRONT LH CORNER PANEL BRACKET <i>not in</i>	1	60.10	60.10	+
FRONT LH DOOR <i>not in</i>	1	2245.20	2245.20	✓
FRONT LH DOOR CHECKER <i>not in</i>	1	96.50	96.50	+
FRONT LH DOOR HINGE (LOWER) <i>not in</i>	1	199.40	199.40	+
FRONT LH DOOR INNER ARCH SEAL <i>not in</i>	1	67.10	67.10	+
FRONT LH DOOR PILLAR (CENTER) <i>Repair</i>	1	573.70	573.70	+
FRONT LH DOOR PILLAR (OUTER) <i>not in</i>	1	587.20	587.20	✓
FRONT LH DOOR WIRE HARNESS <i>not in</i>	1	526.70	526.70	+

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MAXLINES DISTRIBUTORS
92 COMMONWEALTH DRIVE #01-716
COMMONWEALTH 16
SINGAPORE 140092

Contact : 96391418

TAX INVOICE

Repair Code : CLM16406

Date in : 26/08/2024

Vehicle Num. : GBF4531C

Model : TOYOTA HIACE 3.0 M

Chassis/Eng# : KDH2010190610/1KD2592929

FRONT LH DOOR WIRE HARNESS COVER	1	948.10	268 948.10
FRONT LH STEP GARNISH	1	175.40	175.40 ✓
FRONT LH STEP PANEL	1	78.90	78.90 ✓
FRONT SUPPORT PANEL (TOP PANEL)	1	433.90	433.90 ✓
Subtotal before discount			23,041.20
Percentage discount 25%			5,760.30
Sub-total 1			17,280.90
FRONT BUMPER CLIPS - SET	1	80.00	80.00 30
FRONT GRILLE CLIPS - SET	1	40.00	40.00 30
FRONT LH DOOR COMPANY STICKER	1	25.00	25.00 ✓
FRONT LH STEP GARNISH CLIPS - SET	1	30.00	30.00 10
Subtotal before discount			175.00
Percentage discount 0%			0.00
Sub-total 2			175.00
Parts-total			17,455.90

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To remove, change dashboard fascia and transfer where necessary.

80.00 30
80.00 60
450.00 250

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MAXLINES DISTRIBUTORS
92 COMMONWEALTH DRIVE #01-716
COMMONWEALTH 16
SINGAPORE 140092

Contact : 96391418

TAX INVOICE

Repair Code : CLM16406
Date in : 26/08/2024
Vehicle Num. : GBF4531C
Model : TOYOTA HIACE 3.0 M
Chassis/Eng# : KDH2010190610/1KD2592929

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	6,150.00
Parts & Labour Total	23,605.90

2,600.00 1000
2,800.00 1400
140.00 100

2840

*** This is a computer-generated document which requires no signature.***

page 4

Adrian C
L/S 29/08/24
09 Days

total: 1257242
L/S: 10K ✓

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: