

D.O.A : 23 Aug 2024

OWNER : STARK HOLDINGS INN BIKE LEASING PTE LTD

SLG266X Honda Vezel

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear windscreen moulding	\$ 236.80 +
2	1	Rear tailgate	\$ 1,450.30 +
3	1	Rear tailgate inner trim board	\$ 487.80 x
4	1	Rear tailgate lock	\$ 360.80 x
5	1	Rear tailgate logo	\$ 57.10 +
6	1	Rear tailgate rubber	\$ 72.20 +
7	1	Rear tailgate n/s side reflector	\$ 401.20 x
8	1	Rear tailgate "VEZEL" emblem	\$ 61.10 +
9	1	Rear taillamp -LH	\$ 698.70 +
10	1	Rear end panel	\$ 625.70 +
11	1	Rear end panel inner garnish	\$ 101.70 +
12	1	Rear bumper <i>Detached</i>	\$ 1,190.40 765
13	1	Rear bumper lower diffuser	\$ 241.40 +
14	1	Rear bumper lower lid	\$ 825.40 +
15	1	Rear bumper reflector	\$ 60.10 +
16	2	Rear bumper side retainers	\$ 71.60 +
17	2	Rear bumper PDC sensors	\$ 621.00 +
18	2	Rear bumper reverse sensor holders	\$ 60.00 +
19	1	Rear fender -LH	\$ 761.80 +
20	1	Rear fender inner trim board	\$ 546.20 +
21	1	Rear fender wheel arch garnish -LH	\$ 182.40 +
22	1	Rear wheel rim -LH	\$ 950.00 +
23	1	Front door side mirror assy -RH	\$ 745.50 +
			\$ 10,809.20
			less 20%
			\$ 2,161.84
			<u>\$ 8,647.36</u>

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1		Rear windscreen sealant	\$ 80.00 x
2		Rear tailgate inner trim board clip (1 set) <i>3 per set</i>	\$ 50.00 +
3		Rear bumper clip (1 set) <i>per</i>	\$ 50.00 30
4		Rear tyre <i>per set</i>	\$ 500.00 +
			<u>\$ 680.00</u>
Total parts :			\$ 9,327.36

No	Description	Labour Charges
1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00 x
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 180.00 x
3	To remove and refit rear reverse sensor.	\$ 120.00 50
4	To transfer rear tailgate mechanism and wiring assembly to assist repair.	\$ 80.00 x
5	To conduct wheel alignment.	\$ 150.00 x
6	To remove and refit rear windscreen glass.	\$ 180.00 x
7	To apply undercoating on repaired and replaced panel.	\$ 200.00 x
8	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,600.00 2w
9	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,500.00 2w

Total labour :

\$ 4,090.00

Total parts :

\$ 9,327.36

Total labour :

\$ 4,090.00

Total repair cost :

\$ 13,417.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G
1/8 27/08/24.
02 Days.