

Date: 18/06/2024

Vehicle No: SNJ9802A

Model: MERCEDES BENZ S400L

Chassis: WDD2221652A275218-2016

Reg.Year: 2016

Third Party Insurer: MS FIRST CAP

Third Party Veh No: SHC1992U

Date of Accident: 13/06/2024

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1	Bu	\$2,495.00
2	REAR BUMPER SIDE RETAINER RH	1	CM	\$81.00
3	REAR BUMPER PARKING SENSOR	1	in	\$243.00
4	REAR BUMPER CHROME MOULDING RH	1	me	\$162.00
5	REAR TAIL LAMP RH	1	in	\$1,215.00
6	REAR ABSORBER RH 4520	1		\$5,243.00
7	REAR LOWER ARM RH 526	1	By	\$667.00
8	REAR KNUCKLE ARM RH 1958	1	By	\$2,599.00
9	REAR WHEEL BEARING RH	1	me	\$353.00
10	REAR STABILISER LINKAGE RH	1	in	\$181.00
11	REAR FENDER RH	1		REPAIR
SUB TOTAL				\$13,239.00
LESS 10%				-\$1,323.90
PARTS TOTAL				\$11,915.10

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1	me	\$50.00
2	REAR RIM RH 117 950	1	no	\$1,000.00
S/N TOTAL				\$1,050.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

4001
\$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR FENDER RH & ETC.

4401
\$600.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER PARKING SENSOR & ETC.

\$120.00 601

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

nn \$150.00 X

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18/06/2024
 Vehicle No: SNJ9802A
 Model: MERCEDES BENZ S400L
 Chassis: WDD2221652A275218-2016
 Reg.Year: 2016

Third Party Insurer: MS FIRST CAP
 Third Party Veh No: SHC1992U
 Date of Accident: 13/06/2024
 Estimator: TING AN
 Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE REAR ABSORBER RH, REAR LOWER ARM RH,
 REAR KNUCKLE ARM RH, REAR WHEEL BEARING RH & ETC.

\$400.00 200

TO WHEEL ALIGNMENT & BALANCING.

\$100.00 20

TO TUFF KOTE & UNDERSEAL MATERIALS.

na \$120.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 20

LABOUR TOTAL \$2,310.00

TING AN

TOTAL \$15,275.10

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

