

Not Notified
C/Lmp \$3000

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5779M

AAD2408-109

Vehicle No.:

Chassis No.:

UEN No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

20 AUG 2024

SHD5779M

JTDKB3FU503076858

200303878K

TOYOTA

PRIUS

26/08/2024

SHADIS / FCI

15/11/2018

PART

LIST

- 1 PANEL SUB-ASSY, QUARTER, RH
- 1 LINER, REAR WHEEL HOUSE, RH
- 1 MOULDING ASSY, BODY ROCKER PANEL, RH
- 1 PANEL SUB-ASSY, REAR DOOR, RH
- 1 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH
- 1 HANDLE ASSY, REAR DOOR OUTSIDE, RH
- 1 WEATHERSTRIP, REAR DOOR OPENING TRIM, RH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH
- 1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH
- 1 TAPE, BLACK OUT, NO.2 REAR RH
- 1 TAPE, BLACK OUT, NO.3 REAR RH
- 1 TAPE, BLACK OUT, NO.1 REAR RH
- 1 HINGE ASSY, REAR DOOR, LOWER RH
- 1 HINGE ASSY, REAR DOOR, UPPER RH

\$	B	1,099.46	✓
\$	RL	176.09	X
\$	R	624.54	X
\$	B	1,634.33	✓
\$	RL	243.81	X
\$	L	123.06	X
\$	RL	369.60	X
\$	RL	1,161.83	X
\$	RL	260.51	X
\$	RL	44.00	—
\$	RL	19.43	—
\$	RL	27.62	—
\$	R	109.62	X
\$	R	124.74	X

TOTAL \$ 6,018.63

25% \$ 1,504.66

\$ 4,513.97

Special Nett

- 1 DOOR STICKER TEL. NO
- 1 DOOR TRIM CLIP
- 1 DOOR WEATHERSTRIP CLIP
- 1 FENDER LINER CLIP

\$	RL	100.00	Gain
\$	RL	75.00	X
\$	RL	80.00	X
\$	RL	65.00	X

TOTAL \$ 320.00

TOTAL PARTS \$ 4,833.97

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5779M**AAD2408-****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1001
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	601
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	nn X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	7001
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	6601
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	201
TOTAL	\$	5,110.00	
Over All Total	\$	9,943.97	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days**06 Days****5 days**